

# REPORT of SURVEY for REPAIRS, &c.

4829

No. in  
a. Book.

Survey held at

Cardiff

Date, first Survey

Last Survey

13<sup>th</sup> March 1878

S.S. "Tennis"

Master

Inch

Deck

13 1/4

Awning Deck

By whom built

Hitchell

Destined Voyage

Roath Dry Dock

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

Classed

90. A. 1

No.

17416

Port

Swan

Years assigned.

1. '96

Character in Register Book.

## EXAMINATION AS PER RULE

need on Blocks, in Dry Dock for examination of Bottom, which appeared in good condition. And well cleaned and coated with Paint externally

Present Condition of the					
Decks	Good	Treenails	Pivots where seen	Good	Windlass and Capstan
Waterways	"	Breasthooks and Stenson	"	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained
Planksheers	"	Keelsons	not seen	"	Sails
Sheerstrakes	"	Clamps and Shelves	Strips &c	"	Anchors No. of
Topsides	Plating	Ceiling	"	"	Cables
Wales	"	Rudder	"	"	Hawsers and Warps
Plank (Bottom) and Counter	"	Copper	Paint When put on	from	Standing & Running Rigging
Engine Room Skylights		Caulking of			
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	Good		
Scuppers					
Cargo and Main Hatchways					
Hatches					

General Observations, Opinion as to Class, &c.

Vessel appears in good, and efficient condition, eligible to remain as classed 90. A. 1

13 Engineer Surveyor's Report. No

Forwarded herewith

The Amount of Entry Fee ... ..£

Special ... ..£

Certificate (if required) ... ..£

(Travelling Expenses, if any, £

received by me,

28/3 1878

Committee's Minute

2nd April, 1878

Character assigned

90. A. 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019

Lloyd's Register Foundation

IRON477-0240



*J. H. Harris*



© 2019

Lloyd's Register  
Foundation