

ANNUAL SURVEYS.

IRON 477-0259

20664

Rec 8/4/78

No. in Reg. Book. on the No. 14 Survey held at Port Chalmers Date, first Survey 12 Dec 1877 Last Survey 12 Dec 1877

251 on the "Pareora" Lat (White Eagle) Master Power

Tonnage 879 Built at Glasgow When built 1855

By whom built Owners New Zealand Shipping Co

Port belonging to London Destined Voyage London

If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 18994 Port of London Classed Years assigned 1.77 Character in Register Book A1

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchor, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. When put on	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	
Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.		Hatches

In Dry Dock Port Chalmers had bottom cleaned and recoated and is otherwise in first class condition, Decks caulked,

Committee's Minute 24 April 1878 James W Russell
 Character assigned DBW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. in Reg. Book. on the No. 15 Survey held at Port Chalmers Date, first Survey Jan 7 1878 Last Survey Jan 7 1878

311 on the Okaki Master Mc James Devitt

Tonnage 1014 Built at Newcastle When built 1875 - 8 months

By whom built Palmers Owners New Zealand Shipping Co

Port belonging to London Destined Voyage London

If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 18804 Port of London Classed Years assigned 100 A1 Character in Register Book 100 A1

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchor, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. When put on	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.	Scuppers	Cargo and Main Hatchways
General Observations, Opinion as to Class, &c.		Hatches

In Dry Dock at Port Chalmers when she was carefully examined had her bottom cleaned and recoated and decks caulked and is otherwise in first rate condition

Committee's Minute 24 April 1878 James W Russell
 Character assigned 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18