

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey April 21 Last Survey April 23 1878
 No. in on the SS F T Barry Master
 Reg. Book. 6 Tonnage 545 Built at Middlesbrough When built 1872 8 M
 By whom built Backhouse Owners Sixon & Harris
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 19452 Port of Iron
 Present Condition of the
 Decks good Treenails Round good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Foremast broken at bottom, a small caulking plate put on a Port Side Plate.

Classed 100 A 10.77
SS Lin m 277

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c. good & sufficient when they could be seen
 Condition, how ascertained
 Sails
 Anchors, No. of 3 Bn. & 1 Rodge
 Cables
 Hawser and Warps
 Standing and Running Rigging

Committee's Minute 30th April, 1878.
 Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at London Date, first Survey April 6 Last Survey April 8th 1878
 No. in on the Bk Helen Denny Master W Ruth
 Reg. Book. 260 Tonnage 728 Built at Glasgow When built 1866 11 M
 By whom built Suncan Owners Shaw Saville & Co
 Port belonging to Southampton Destined Voyage
 If Surveyed Afloat or in Dry Dock by HK

Last Survey, No. 18490 Port of Iron
 Present Condition of the
 Decks good Treenails Round good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder broken
 Plank (Bottom) and Counter Copper or Y.M. broken When put on none
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. Bottom scraped & braced

Classed 100 A 5.76
SS Lin m 176

Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c. good & sufficient when they could be seen
 Condition, how ascertained
 Sails
 Anchors, No. of 3 Bn. & 1 Rodge
 Cables
 Hawser and Warps
 Standing and Running Rigging

Committee's Minute 30th April, 1878.
 Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18