

20739

Report of Survey for Repairs of Engines and Boilers.

No. _____
No. in Reg. Book. Survey held at London Date, first Survey _____ Last Survey 7th January 1878
on the Screw Steamer Maripia Master _____
Tons _____ Owners Wapco Smitapio Port belonging to Lisbon Classed _____ Years assigned _____ Character in Register Book _____

Diameter of Cylinder 30 1/2 Engines Comp London When made 1878
Length of Stroke 30 By whom made Seward & Co
Pressure of Steam 65 lb.
Registered Horse Power _____

Particulars of Repairs and Examination "New Boilers fitted, Engines compounded by fitting 2 new cylinders. New pumps, New bunker plating. Sea cocks in stoke hold removed from flat of bottom and new cocks fitted to turn of bilge. Crank shaft examined, found a few flaws in it but not thought sufficient to condemn it. Propeller & Sea connections examined in Dry Dock. The machinery generally overhauled. New
It is submitted that a certificate be granted for 12 months only, the shaft to be examined at the expiration of that period."

Entered pursuant to
Mpp. Gules 400
7/6/78

The Amount of Fee ... £ : : received by me, }
Certificate (if required) ... £ : : 187 }
(Travelling Expenses, if any, £)

Committee's Minute 14th May 1878

William Parker
James Mutton
Engineer Surveyors to Lloyd's Register of British & Foreign Shipping.

12 months, 78

(The Surveyors are requested not to write on or below the space for Committee's Minute).