

ANNUAL SURVEYS.

20848

No. in Reg. Book. **No. 4648** Survey held at **Loole** Date, first Survey **2nd April** Last Survey **3rd April** 1878
 on the **Reg. No. 2. "Marram Briggs"** Master **Skidwood**
 Tonnage **630** Built at **S. Shields** When built **1864**
 By whom built **Readhead** Owners **Corkshire Coal & Steam Ship Co. Ltd.**
 Port belonging to **Loole** Destined Voyage **Hamburg**
 If Surveyed Afloat or in Dry Dock **Afloat**

Last Survey, No. **20267** Port of **Iron**
 Present Condition of the Decks **Good** **Rails** **When seen** **Good** **Greenails**
 Waterways **do** Breasthooks and Stemson **do**
 Comings **do** Transoms, Pointers, and Crutches **do**
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do**
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do**
 Planksheers **do** Keelsons **do**
 Sheerstrakes **do** Clamps and Shelves **do**
 Topsides **do** Ceiling **do**
 Wales **do** Rudder **do**
 Plank (Bottom) and Counter **do** Copper or Y.M. **do** When put on **do**
 Engine Room Skylights **Good** Caulking of Bottom, Deck, & Waterways **Good**
 General Observations, Opinion as to Class, &c. **The Riggers having been taken out for repairs examined the iron work and cementing under same, as well as the rivets generally, & as far as practicable. Cementing of flat under Riggers repaired and the inside iron work in folds painted. Eligible in my opinion to remain as classed. Engineer's Report now forwarded**

Committee's Minute **14th May 1878**
 Character assigned **TRW 90A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18

No. **—** Survey held at **Foull** Date, first Survey **2nd May** Last Survey **—** 1878
 on the **Reg. No. 2. "Stithella"** Master **Whiting**
 Tonnage **1281** Built at **Lundeland** When built **1845**
 By whom built **Plummer** Owners **Jackson, Beaumont & Co.**
 Port belonging to **Foull** Destined Voyage **—**
 If Surveyed Afloat or in Dry Dock **In Slipway**

Last Survey, No. **19467** Port of **Iron**
 Present Condition of the Decks **Good** **Rails** **When seen** **Good** **Greenails**
 Waterways **do** Breasthooks and Stemson **do**
 Comings **do** Transoms, Pointers, and Crutches **do**
 Upper Deck Beams & Fastenings **do** Timbers of the Frame at the Openings **do**
 Lower Deck Beams & Fastenings **do** Ditto ditto at other places **do**
 Planksheers **do** Keelsons **do**
 Sheerstrakes **do** Clamps and Shelves **do**
 Topsides **do** Ceiling **do**
 Wales **do** Rudder **do**
 Plank (Bottom) and Counter **do** Copper or Y.M. **do** When put on **do**
 Engine Room Skylights **Good** Caulking of Bottom, Deck, & Waterways **Good**
 General Observations, Opinion as to Class, &c. **Placed on blocks on Slipway and the bottom cleaned and painted. Is in good condition and eligible in my opinion to remain as classed.**

Committee's Minute **14th May 1878**
 Character assigned **90A1**
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) **Paid** 18