

REPORT of SURVEY for REPAIRS, &c.

20945
18/5/78

No. in Reg. Book. **No. 26034** Survey held at Liverpool Date, first Survey April 13 Last Survey May 3 1878
 on the (Iron) Bk "Earl Granville" Master Campbell
 TONNAGE under Tonnage Deck 900 Built at Glasgow When built 1877 3
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Deck
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1000 Owners McAlister & Sons Port belonging to Glasgow
 Crew Space, as per Rule
 Register Tonnage, out on Beam 956 Residence Glasgow
 Engine Room By whom built Funcan Destined Voyage Australia
 Reg. Tons as St'mer, cut on Bm. If Surveyed Afloat or in Dry Dock Afloat in Cannery dry dock
 Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned _____ Character in Register Book 100 A1
 Last Survey, No. 18037 Port Liver Classed _____

REPAIRS, OR EXAMINATION AS PER RULE

Now supplied in lieu of others lost - viz -
 1 B. Anchor 27.3-0 *as stock Lloyd's Netherlon test = 26.10.3-0. J.G. Lewis April 9/78*
 1 B. " 23.3-6 *" " " = 23.14.2-21. J.G. " J.G. 9/78*
 45 fms & 2 fms of 1 1/4" B Cable *" " " = 51.5. " J.G. " J.G. 9/78*
 30 " " 2" " 1 1/4" " *" " " = 55.2.2. J.G. " J.G. 9/78*
 Breasting strain applied to 3 Leads cut on each length of 15 fathoms = 7 1/4 tons
 The bottom scraped and painted.

Present Condition of the Decks	<u>Good</u>	Transoms	<u>Good</u>	Windlass and Capstan	<u>Good & efficient</u>
Waterways	"	Breasthooks and Stems	"	Pumps	" "
Comings	"	Transoms, Pointers, and Crutches	"	Boats	" "
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	" "
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<u>seen from deck</u>
Planksheers	_____	Keelsons	"	Sails	<u>Good</u>
Sheerstrakes	"	Clamps and Shelves	_____	Anchors No. of	}
Topsides	"	Ceiling	"	Cables	
Wales	"	Rudder	"	Hawsers and Warps	}
Plates	"	Copper <u>Cen</u> When put on <u>77</u>	"	Standing & Running Rigging	
Plank (Bottom) and Counter	"	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>
Engine Room Skylights	_____	Coal Bunker, Openings, Lids, &c.	_____	Hatches	<u>Good</u>
General Observations, Opinion as to Class, &c.	_____				

This vessel is now in good condition and in my opinion eligible to remain as Classed.

The Amount of Entry Fee£ : : received by me, } J. F. L.
 Special£ 1 : 1 : 16/5-1878
 Certificate (if required)£ : :
 (Travelling Expenses, if any, £ _____)
 Committee's Minute Liverpool May 17th 1878
 Character assigned 100 A1.

J. F. L.
 Surveyor to Lloyd's Register of British and Foreign Shipping.

 Lloyd's Register Foundation

Cause of Repairs to be clearly stated.

IRON 478-0065

Carl Granville

260341



© 2019

Lloyd's Register
Foundation