

ANNUAL SURVEYS.

No. 78 Survey held at London Date, first Survey 17th May Last Survey 20th May 1878.
 No. in on the Bk. "Ganymede" Master W. Brown
 Reg. Book. 78 Tonnage 569 Built at Punderland When built 1868 - 1 mo
 By whom built Doxford Owners Thompson &
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Horseferry Dry Dock

Last Survey, No. 17432 Port of Iron Classed 11.76
 Present Condition of the
 Decks good Rivets where seen good
 Waterways do Breasthooks and Stenson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places -
 Planksheers good Keelsons good where seen
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling do do
 Wales do Rudder do
 Plating (Bottom) and Counter good Copper or Y.M. - When put on -
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights - Coal Bunker, Openings, Lids, &c. - Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c. The vessel has been in dry dock, bottom cleaned and recoated with two coats of Composition. Inside examined with Ballast in hold but where seen she was found to be in a good condition and in my opinion eligible to remain as classed.

Committee's Minute 31st May. 1878.
 Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18

No. 261 Survey held at London Date, first Survey 21st May Last Survey 22nd May 1878.
 No. in on the S. "Carmarthen Castle" Master H. James
 Reg. Book. 261 Tonnage 1407 Built at Liverpool When built 1874 - 11 mo
 By whom built Evans Owners Richards, Mills & Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 18736 Port of Iron Classed 100A.1.
 Present Condition of the
 Decks good Rivets where seen good
 Waterways do Breasthooks and Stenson do do
 Comings do Transoms, Pointers, and Crutches do do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places -
 Planksheers do Keelsons where seen good
 Sheerstrakes do Clamps and Shells do do
 Topsides do Ceiling do do
 Wales do Rudder do do
 Plating (Bottom) and Counter good Copper or Y.M. - When put on -
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights - Coal Bunkers, Openings, Lids, &c. - Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c. The vessel has been placed in dry dock, bottom cleaned and recoated with three coats of Composition. Hold examined with Ballast and dunnage therein, but where seen was found to be in a good condition and in my opinion eligible to remain as classed.

Committee's Minute 31st May. 1878.
 Character assigned 100A.1

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) 18