

ANNUAL SURVEYS. 21010.

No. 12979 Survey held at Newcastle Date, first Survey and Last Survey 13th May 1878
 No. in on the Iron S.S. "Rowena" Master W. Stacey
 Reg. Book. 621 Tonnage 1002 Built at Newcastle When built 1868 - 6 mo
 By whom built Mitchell Owners Adams & Short
 Port belonging to Newcastle Destined Voyage Cronstadt
 If Surveyed Afloat or in Dry Dock Wallend Slip

Last Survey, No. 18998 Port of Newcastle Classed AI Years assigned 7.77 Character in Register Book.
 Present Condition of the Decks Good Freenails Rivets Good
 Waterways do. Breasthooks and Stemson do. S.S. Two No 2-77
 Comings do. Transoms, Pointers, and Crutches do. Windlass and Capstan Good
 Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do. Pumps do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do. Boats do.
 Planksheers do. Keelsons do. Masts, Yards, &c. do.
 Sheerstrakes do. Clamps and Shelves Stringers do. Condition, how ascertained From the deck
 Topsides do. Ceiling do. Sails Sufficient & Good.
 Wales do. Rudder do. Anchors, No. of do.
 Plank (Bottom) and Counter do. Copper or Y.M. ✓ When put on ✓ Cables do.
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good.
 General Observations, Opinion as to Class, &c.

The bottom cleaned and recoated, she appears to be in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 28th May. 1878. J. H. Cooke.
 Character assigned AI Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18

No. 12979 Survey held at Newcastle Date, first Survey and Last Survey 15th May 1878
 No. in on the Iron S.S. "St. Rio" Master W. J. Irvine
 Reg. Book. 1047 Tonnage 1149 Built at Newcastle When built 1875 - 8 mo
 By whom built Swan Owners Hall, Blackburn & Co
 Port belonging to South Shields Destined Voyage Port Said
 If Surveyed Afloat or in Dry Dock Wallend Slip

Last Survey, No. 19772 Port of Iron Classed 100 AI Years assigned 4.77 Character in Register Book.
 Present Condition of the Decks Good Freenails Rivets Good
 Waterways do. Breasthooks and Stemson do. Windlass and Capstan Good
 Comings do. Transoms, Pointers, and Crutches do. Pumps do.
 Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do. Boats do.
 Lower Deck Beams & Fastenings do. Ditto ditto at other places do. Masts, Yards, &c. do.
 Planksheers do. Keelsons do. Condition, how ascertained From the deck
 Sheerstrakes do. Clamps and Shelves Stringers do. Sails Sufficient & Good
 Topsides do. Ceiling do. Anchors, No. of do.
 Wales do. Rudder do. Cables do.
 Plank (Bottom) and Counter do. Copper or Y.M. ✓ When put on ✓ Hawesers and Warps do.
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good.
 General Observations, Opinion as to Class, &c.

The bottom cleaned and recoated, she appears to be in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute 28th May. 1878. J. H. Cooke.
 Character assigned 100 AI Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) TRW Paid 18