

ANNUAL SURVEYS.

37,305

Survey held at London Date, first Survey May 17 Last Survey June 21st 1878
 in on the S Barossa Master H. J. Walker
 Book. Tonnage 968 Built at Sunderland When built 1873 - 5M
 By whom built Pile Owners J. B. Walker
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 18452 Port of Iron

Classed 100A-5-77
 Years assigned. SS Len M-77
 Character in Register Book.

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Corten</u> When put on <u>new</u>	
Engine Room Skylights		Caulking of	
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>
General Observations, Opinion as to Class, &c.		Scuppers	<u>Good</u>
		Cargo and Main Hatchways	<u>Good</u>
		Hatches	<u>Good</u>

Windlass and Capstan _____
 Pumps _____
 Boats _____
 Masts, Yards, &c. Good &
 Condition, how ascertained sufficient
 Sails where
 Anchors, No. of 3 Bm. 2 V. 1 J. 1 they
 Cables could
 Hawser and Warps be seen
 Standing and Running Rigging _____

*She is now in good condition
 and entitled to remain as classed*

Senhouse Martindale

Committee's Minute 28th June, 1878.

Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 220 Survey held at London Date, first Survey May 11th Last Survey June 21st 1878
 in on the BK Westbury Master Wm. G. Cook
 Reg. Book. Tonnage 493 Built at Sunderland When built 1867 - 4M
 By whom built Pile Owners J. B. Walker
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Dry Dock

Last Survey, No. 18619 Port of Iron

Classed A-6-77
 Years assigned. SS Len M-75
 Character in Register Book.

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Corten</u> When put on <u>new</u>	
Engine Room Skylights		Caulking of	
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>
General Observations, Opinion as to Class, &c.		Scuppers	<u>Good</u>
		Cargo and Main Hatchways	<u>Good</u>
		Hatches	<u>Good</u>

Windlass and Capstan _____
 Pumps _____
 Boats New Mizen Mast &
 Masts, Yards, &c. Mizen Mast Good &
 Condition, how ascertained sufficient
 Sails where
 Anchors, No. of 3 Bm. 2 V. 1 J. 1 they
 Cables could
 Hawser and Warps be seen
 Standing and Running Rigging _____

*She is now in good condition
 and entitled to remain as classed*

Senhouse Martindale

Committee's Minute 28th June, 1878.

Character assigned 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____