

Report of Survey for Repairs of Engines and Boilers.

(Recd 7-6-78)

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey

May 30th

Last Survey

May 31st

1878

584 on the

S.S. "Lloyds"

Master

Tons

564
499

Owners

Dixon & Harris

Port belonging to

London

Classed

Years
assigned.

Character in Register Book.

A 1

Diameter of Cylinder

25 x 50

Length of Stroke

33

Engines made at

Newcastle

When made

1869

Pressure of Steam

64 lb

By whom made

Palmer's Co.

N.B. 76

Registered Horse Power

160

Particulars of Repairs and Examination

as required for Special Survey

No. 2.

Sea cocks and connections examined found good.

Propeller tightened up on shaft, and new tips to blade

fitted; Crank shaft examined and found good.

Boiler examined and found in good condition

It is submitted that this vessel is eligible to remain

as classed and to have a new machinery certificate

granted and Lloyds M.C. 5.78 recorded.

The Amount of Fee ... 7/6/77 ... £ 2 : 2 : 0 received by me,

Certificate (if required) ... £ : : 21 June 1878

(Travelling Expenses, if any, £)

Committee's Minute

11th. June

1878.

James Multon
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.