

REPORT of SURVEY for REPAIRS, &c.

No. 4328 Survey held at Cardiff Date, first Survey 9th Last Survey 15th May 1878
 Reg. Book. 15th on the S. S. "President" Master Blunckhorn
 Tonnage under Tonnage Deck 1342 Built at Sunderland When built 1844 8
 Ditto of Spar Deck, or Awning Deck Owners J. Westall Port belonging to Sunderland
 Ditto of Poop Residence Sunderland
 Ditto of Raised Qr. Dk. By whom built Portman Destined Voyage Port Said
 Ditto of Houses on Deck 1428 Hilli & Bate Dry Dock
 Ditto of Forecastle 924 ft. Surveyed Afloat or in Dry Dock
 Gross Tonnage 1428 ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Crew Space, as per Rule 100 A.1
 Register Tonnage, cut on Beam 9.77
 Engine Room 100 A.1
 Reg. Tons as St'mer, cut on Bm. 9.77
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Last Survey, No. 19315 Port Iron
 REPAIRS, OR EXAMINATION AS PER RULE On acct of Damage

Placed on blocks in Dry Dock. A fore plate on the port bow, holed, and fractured by anchor at the S. water mark, cut, and new fore length fitted connected to the remaining portion of plate by broad liner butt strap, extending from frame to frame. Bottom well cleaned, and coated with Paint & Gallow.

Present Condition of the	Good	Stumps	Good	Windlass and Capstan	Good
Decks	Good	Treenails	Good	Pumps	Good
Waterways	"	Breasthooks and Stemson	"	Boats	"
Comings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Condition, how ascertained	and
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors No. of	Sufft
Sheerstrakes	"	Clamps and Shells	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper	"	Cargo and Main Hatchways	"
Engine Room Skylights	"	Caulking of	"	Hatches	"
Coal Bunker, Openings, Lids, &c.	"	Bottom, Deck, & Waterways	"		
Scuppers	"		"		

General Observations, Opinion as to Class, &c.

Vessel appears in good, and efficient condition, eligible to remain as classed 100 A.1

The Amount of Entry Fee ... £ : : received by me, 1878
 Special ... £ 2 : 2 :
 Certificate (if required) ... £ : :
 (Travelling Expenses, if any, £)

Committee's Minute 11th June 1878

Character assigned 100 A.1

Henry L. Syrell
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
 Lloyd's Register
 Foundation
 120474-0028