

ANNUAL SURVEYS.

Rec. 3.7.78

No. in Reg. Book. **No.** 56 Survey held at London Date, first Survey June 21 Last Survey June 24 1878
 on the SS Tanfield Master G. Bowdell
 Tonnage 587 Built at Newcastle When built 1864 12.
 By whom built Palmer Owners J. Pennick & Sons
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By SR

Last Survey, No. 19002 Port of Iron
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on nm
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Classed AC 1 7-77
 Years assigned. Character in Register Book.
SS Tanfield

She is now in good condition and entitled to remain as Classed. The Chain Cables have been on deck and examined 270 fathoms in all.

Committee's Minute 9th July 1878.

Character assigned AC 1 nm

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. in Reg. Book. **No.** 660 Survey held at London Date, first Survey June 21 Last Survey July 2 1878
 on the S Sierra Morena Master _____
 Tonnage 1885 Built at Sunderland When built 1875 2M
 By whom built Arncliffe Owners Thompson Anderson & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock By SR

Last Survey, No. 15389 Port of Iron
 Present Condition of the Decks Good Treenails Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder Enlarged at aft side below
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on nm
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Classed 100A 11.75
 Years assigned. Character in Register Book.
S Sierra Morena

She is now in good condition and entitled to remain as Classed.

Committee's Minute 9th July 1878.

Character assigned 100A 1 nm

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____