

REPORT of SURVEY for REPAIRS, &c.

No. *4341*

No. in
Reg. Book.

Survey held at *Newport*

Date, first Survey *10th*

Last Survey *17th April 1878*

on the *S.S. Tyndale*

Master *C. Evans*

TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St^rmer, cut on Bm.

Built at *Sunderland*

When built

YEAR.

MONTH.

1868

2

Owners *Barrow & Co. Ltd. St. Helens*

Port belonging to

Barrow

Residence *Barrow*

By whom built *Laird*

Destined Voyage *Spain*

Surveyed Afloat or in Dry Dock

Newport Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

18836

Port

Iron

Classed

B 1

SS Reg 174, 6.77

REPAIRS, OR EXAMINATION AS PER RULE

S.S. No. 2

Placed on Bloes in Dry Dock, Bottom cleaned & coated with Paint; Platform taken off Tank, aft, and ceiling in Forehold removed as per Rule, ceiling Batten taken down, keel examined and found generally in very good condition, a few places repaired. Inner surface of plating, frames, beams, stringers &c, all chipped & beaten clean, and well coated with Paint. Angle Irons on two beams repaired, also some lengths on main keelson, and Ribber plate added to strengthen the same. The ceiling repaired where required, and the Tank "unrusted" and tested as per Rule, and a few Rivets in Top renewed, cables ranged on Deck and examined with anchors & equipment, and the Winches unhung, partially stripped for examination. Portions of the Deck repaired, and Caulked.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine-Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shells

Ceiling

Rudder

Copper

Bottom, Deck, & Waterways

Caulking of

When put on

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ...

Special ...

Certificate (if required) ...

(Travelling Expenses, if any, £ 1. 1. 0)

Committee's Minute

5th July

1878.

Character assigned

B 1

SS No 2-78

received by me,

29/6 1878

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

120479-100

Synedale



© 2019

Lloyd's Register
Foundation