

ANNUAL SURVEYS.

No. 51 Survey held at London Date, first Survey 10th Augt Last Survey 10th Augt 1878
 on the Bk "Natal" Master J. Smith
 Reg. Book. 51 Tonnage 446 Built at Sherdeen When built 1876 - 12 mo
 By whom built A Hall & Co Owners J J Rennie
 Port belonging to Sherdeen Destined Voyage Natal
 If Surveyed Afloat or in Dry Dock Ratcliffe Cross Dry Dock & Afloat

Last Survey, No. 19402 Port of Iron Character in Register Book. 100 A.1
 Present Condition of the Decks Good
 Waterways do Breasts Rivets Good
 Comings do Breasthooks and Stemson "
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches "
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings "
 Planksheers do Ditto ditto at other places "
 Sheerstrakes do Keelsons "
 Topsides do Clamps and Shelves "
 Wales do Ceiling "
 Plank (Bottom) and Counter do Rudder "
 Engine Room Skylights do Copper or Y.M. When put on
 General Observations, Opinion as to Class, &c. Good Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained From Deck
 Sails Good and sufficient
 Anchors, No. of 3 B. 1 S. 1 H.
 Cables Not Ranged
 Hawsers and Warps Good & sufficient
 Standing and Running Rigging Good
 Good Hatches Good

Committee's Minute 16th. August, 1878. Geo J Rickard
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 829 Survey held at London Date, first Survey 8th Augt Last Survey 9th Augt 1878
 on the Screw Ste "City of Ghent" Master J. Grant
 Reg. Book. 829 Tonnage 125 Built at Grimsby When built 1871 - 1
 By whom built Charlton Owners D.C Thomas
 Port belonging to London Destined Voyage "
 If Surveyed Afloat or in Dry Dock Gridiron off Mountani Dock

Last Survey, No. 17860 Port of Iron Character in Register Book. A.1
 Present Condition of the Decks Good
 Waterways do Breasts Rivets where seen Good
 Comings do Breasthooks and Stemson do
 Upper Deck Beams & Fastenings do Transoms, Pointers, and Crutches do
 Lower Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Planksheers do Ditto ditto at other places do
 Sheerstrakes do Keelsons do
 Topsides do Clamps and Shelves do
 Wales do Ceiling do
 Plank (Bottom) and Counter do Rudder do
 Engine Room Skylights Good Copper or Y.M. When put on
 General Observations, Opinion as to Class, &c. Good Caulking of Bottom, Deck, & Waterways Good
 Windlass and Capstan Good
 Pumps do
 Boats do
 Masts, Yards, &c. do
 Condition, how ascertained From Deck
 Sails Good and sufficient
 Anchors, No. of 3 B. 1 S. 1 H.
 Cables Not ranged Good
 Hawsers and Warps Good and sufficient
 Standing and Running Rigging Good
 Good Hatches Good

Committee's Minute 16th. August, 1878. Geo J Rickard
 Character assigned A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18