

Report of Survey for Repairs of Engines and Boilers.

21575

(Resd 28.6.78)

No.

No. in
Reg. Book.

Survey held at

Weyford.

Date, first Survey

Last Survey

7th June

1878.

615
637

on the S.S. Granton

Master

Tons

816

Owners

Genl Steam Navigation Co. Ltd. belonging to London

Classed

Years
assigned.

Character in Register Book.

100A1

Diameter of Cylinder

56

Length of Stroke

36

Engines made at

Bundee

When made

1866.

Pressure of Steam

28 lbs.

By whom made

Gourlay

Registered Horse Power

230

Particulars of Repairs and Examination

Cylinders bored out and

liners fitted, slides examined & found good, cylinder
faces refaced, patch fitted to bottom of main pump
other pump overhauled, Machinery generally
overhauled, New main boiler and mounting
fitted complete, New donkey boiler fitted,
working pressure 50 lbs per square inch.
The machinery and boiler are now in good order
and safe working condition, and render the
vessel eligible to remain as classed and to
have the notification Lloyd's M.C., ~~recorder~~
and N/B 78 recorded

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

(The Surveyors are requested not to write below the space for Committee's Minute.)

The Amount of Fee ... £ 4:44:00 received by me,

Certificate (if required) ... £ : : 24th July 1878

(Travelling Expenses, if any, £)

Committee's Minute

24th July,

1878.

James Milton

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



© 2019

Lloyd's Register

120479-0472

It is submitted that
the results slightly
to have new machine
certificate granted
and Lloyd MC
6.78 recorded
M 29/6/78



© 2019

Lloyd's Register
Foundation