

REPORT of SURVEY for REPAIRS, &c.

21619

No. 4712 Survey held at Glasgow Date, first Survey 12th August Last Survey 29th August 1877
 Reg. Book. 190 on the Iron Ship Canterbury Master Leslie

Official Number 1196
 Tonnage under Tonnage Deck 1196
 Ditto of Spar Deck, or Avning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1300
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 1245
 Engine Room
 Reg. Tons as S^rmer, cut on Bm.

Built at P Glasgow When built 1874 YEAR. MONTH.
 Owners Albion Shipping Co Port belonging to Glasgow
 Residence 15 St. Vincent Place, Glasgow
 By whom built Duncan Destined Voyage
 If Surveyed Afloat or in Dry Dock Govan graving dock & afloat

Length of Poop — ft. Ditto, Forecastle — ft. Ditto, Raised Quarter Deck — ft.
 Last Survey, No. 19183 Port Glasgow Character in Register Book. 100A1
 Classed 100A1 9.77.

REPAIRS, OR EXAMINATION AS PER RULE S.S. No 1
Hatches equal to the timber boards and one stroke of ceiling
in hold on each side lifted. The cement found in good condition
the bottom outside scraped and recoated.

Cause of Repairs to be clearly stated.

Present Condition of the Decks	<u>Good</u>	Treenails Rivets	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>✓</u>	Breasthooks and Stemson	<u>✓</u>	Pumps	<u>✓</u>
Comings	<u>✓</u>	Transoms, Pointers, and Crutches	<u>✓</u>	Boats	<u>✓</u>
Upper Deck Beams & Fastenings	<u>✓</u>	Timbers of the Frame at the openings	<u>✓</u>	Masts, Yards, &c.	<u>✓</u>
Lower Deck Beams & Fastenings	<u>✓</u>	Ditto Ditto at other places	<u>✓</u>	Condition, how ascertained	<u>from the deck</u>
Planksheers	<u>✓</u>	Keelsons	<u>✓</u>	Sails	<u>Said to be complete</u>
Sheerstrakes	<u>✓</u>	Clamps and Shelves	<u>✓</u>	Anchors No. of	<u>3 B. 15 2K</u>
Topsides	<u>✓</u>	Ceiling	<u>✓</u>	Cables	<u>Said to be complete</u>
Wales	<u>✓</u>	Rudder	<u>✓</u>	Hawsers and Warps	<u>Good</u>
Plank (Bottom) and Counter	<u>✓</u>	Copper Cement When put on	<u>74</u>	Standing & Running Rigging	<u>do</u>
Engine Room Skylights	<u>✓</u>	Caulking of	<u>✓</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>✓</u>	Bottom, Deck, & Waterways	<u>Good</u>	Hatches	<u>Good</u>
Scuppers	<u>✓</u>				

General Observations, Opinion as to Class, &c.
This ship is in good and efficient condition, eligible to
remain as classed and to be rated S.S. Cl. No 1. 70

The Amount of Entry Fee£ : : : received by me, } Aug 24th
 Special£ 3 : 3 : } Aug 24th 1878
 Certificate (if required)£ : : :
 (Travelling Expenses, if any, £)
 Committee's Minute 30th. August, 1878.
 Character assigned 100A1
S.S. No 1-70

A. Thompson
 Surveyor to Lloyd's Register of British and Foreign Shipping.



[4,000-18/678.]

IRON 480-0024