

ANNUAL SURVEYS.

No. 26201 Survey held at Liverpool Date, first Survey Sep 10th Last Survey Sep 11th 1878
 No. in on the Ship "Berkshire" Master Euningham
 Reg. Book. 330 Tonnage 1472 Built at Glasgow When built 1867 - 12 mo
 By whom built Barclay Owners E. Marshall.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock.

Last Survey, No. 18966 Port of London Classed S.S. Dun No 2-76. Years assigned. 7.77. Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Rivets. Good
 Waterways 4 Breasthooks and Stems 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shelves _____
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 67
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool 24 Sept 1878 L. Shilston-
 Character assigned *A1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. ✓ Survey held at Liverpool Date, first Survey Sep 11th Last Survey Sep 12th 1878
 No. in on the Ship "Baroda" Master Ellery-
 Reg. Book. 92 Tonnage 1364 Built at Belfast When built 1864 - 4 mo.
 By whom built Harland Owners Brocklebank
 Port belonging to Liverpool Destined Voyage Calcutta.
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock.

Last Survey, No. 17087 Port of London Classed S.S. Liv No 3-76. Years assigned. 10.76. Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Rivets. Good
 Waterways 4 Breasthooks and Stems 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shelves _____
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 64
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.
Bottom sighted, cleaned and coated with paint, and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool 24 Sept 1878 L. Shilston-
 Character assigned *A1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

Berkshire

Baroda

26204



© 2019

Lloyd's Register
Foundation