

ANNUAL SURVEYS.

No. 4730 Survey held at Glasgow Date, first Survey 2nd Sept Last Survey 6th Sept 1878
 No. in on the S. S. Corcyra Master Beaton
 Reg. Book. 1249 Tonnage 494 Built at Stockton When built 1862 - 7mo.
 By whom built Richardson Owners Palgrave Murphy & Co
 Port belonging to Dublin Destined Voyage Q ports
 If Surveyed Afloat or in Dry Dock On Pointhouse Slip and Afloat

Last Survey, No. 20032 Port of Irish

Classed A1 Years assigned. 1.88 Character in Register Book. S.S. no. 3-76

Present Condition of the Decks	<u>Good</u>	<u>ribs</u>	<u>Good</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>
Upper Deck Beams & Fastenings	<u>do</u>	<u>Timbers</u> of the Frame at the Openings	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	<u>ditto</u> at other places	<u>do</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>
Sheerstrakes	<u>do</u>	<u>Keelsons and Securities</u>	<u>do</u>
Topsides	<u>do</u>	Ceiling	<u>do</u>
Wales	<u>do</u>	Rudder	<u>do</u>
<u>Plating</u> (Bottom) and Counter	<u>do</u>	<u>Coating</u> When put on <u>Now</u>	
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways	<u>Hatches</u>
		Windlass and Capstan	<u>Good</u>
		Pumps	<u>do</u>
		Boats	<u>do</u>
		Masts, Yards, &c.	<u>do</u>
		Condition, how ascertained	<u>By examination</u>
		Sails	<u>Well Found</u>
		Anchors, No. of	<u>3 B. 1 S. 2 K.</u>
		Cables	<u>Complete</u>
		Hawsers and Warps	<u>Well Found</u>
		Standing and Running Rigging	

On account of damage - vessel placed on slip bottom scraped and examined, and re-coated: Repaired, covering board of Forecastle and scaling piece, main topgallant rail, main rail, and bulwark stankions. Is now in good and efficient condition eligible to remain as classed

Committee's Minute 46 October 1878

Character assigned A1

Saml. Laphorn

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) 5/- Paid 20th Sept 1878
Survey Fee £1-1-0

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 _____

No. in on the _____ Master _____
 Reg. Book. _____ Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____

Classed _____ Years assigned. _____ Character in Register Book. _____


Present Condition of the Decks	Treenails	
Waterways	Breasthooks and Stemson	
Comings	Transoms, Pointers, and Crutches	Windlass and Capstan
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Pumps
Lower Deck Beams & Fastenings	Ditto ditto at other places	Boats
Planksheers	Keelsons	Masts, Yards, &c.
Sheerstrakes	Clamps and Shelves	Condition, how ascertained
Topsides	Ceiling	Sails
Wales	Rudder	Anchors, No. of
Plank (Bottom) and Counter	Copper or Y.M. When put on	Cables
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Hawsers and Warps
Coal Bunkers, Openings, Lids, &c.		Standing and Running Rigging
General Observations, Opinion as to Class, &c.		
	Scuppers	Cargo and Main Hatchways
		Hatches

Committee's Minute _____ 18 _____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____



© 2019

Lloyd's Register Foundation

IRON 480-0296