

ANNUAL SURVEYS.

21825 + 7.54

Survey held at London Date, first Survey 21 Sep Last Survey 2 Oct 1878.
 on the S. S. "Glenlyon" Master Wallace
 Tonnage 1373 Built at Glasgow When built 1872 - 10 yrs
 By whom built Lon. & Glas. C. Owners A. C. Gow & Co.
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Green's Dry Dock

Last Survey, No. 20464 Port of London Classed 100 A.1.
 Present Condition of the Decks good Rivets wh. seen, good
 Waterways do Breasthooks and Stemson do do
 Comings do Transoms, Pointers, and Crutches do do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do do
 Lower Deck Beams & Fastenings do Ditto ditto at other places not seen
 Planksheers do Keelsons where seen, good
 Plating do Clamps and Shelves do do
 Rudder do do Ceiling do do
 Sides do Copper or Y.M. — When put on —
 Bottom (Bottom) and Counter do Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunker, Openings, Lids, &c. good Scuppers do Cargo and Main Hatchways do Hatches do
 General Observations, Opinion as to Class, &c. The vessel has been placed in dry dock, bottom cleaned, examined and recoated. Hold examined where possible, where seen found in good condition, and she is, in opinion, eligible to remain as classed.

Committee's Minute 8th October, 1878. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 100 A.1. Certificate (if required) _____ Paid _____ 18 _____

Survey held at London Date, first Survey 25 Sep Last Survey 25 Sep 1878.
 on the S. "Western Monarch" Master J. Watson
 Tonnage 1315 Built at Banow When built 1875 - 8 yrs
 By whom built Banow Sh. B. C Owners Ryl. Exchange Ship Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry Dock

Last Survey, No. 19743 Port of London Classed 100 A.1.
 Present Condition of the Decks good Rivets wh. seen, good
 Waterways do Breasthooks and Stemson do do
 Comings do Transoms, Pointers, and Crutches do do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do do
 Lower Deck Beams & Fastenings do Ditto ditto at other places not seen
 Planksheers do Keelsons where seen good
 Plating do Clamps and Shelves do do
 Rudder good Ceiling do do
 Bottom (Bottom) and Counter do Copper or Y.M. — When put on —
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers do Cargo and Main Hatchways good Hatches do
 General Observations, Opinion as to Class, &c. Vessel has been placed in dry dock, bottom cleaned, examined and recoated. Hold examined with ballast therein, but where seen she was found in a good condition and is eligible, in my opinion to remain as classed.

Committee's Minute 8th October, 1878. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Character assigned 100 A.1. Certificate (if required) _____ Paid _____ 18 _____