

# REPORT of SURVEY for REPAIRS, &c.

No.

No. in  
Reg. Book.

Survey held at

London

Date, first Survey

Sept 7<sup>th</sup>

Last Survey

Sept 17<sup>th</sup> 1878

1878

350 on the

SS Albionian

Master

Indair

YEAR.

MONTH.

TONNAGE under Tonnage Deck

1165

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1240

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St<sup>r</sup>mer, cut on Bm.

1011

Built at

Glasgow

When built

1855

Owners W Brown Thomson & Co

Port belonging to

Gull

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock Pontoon

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

29588

Port

Swan

Classed

500A 3-75

SS Hull No 176

REPAIRS, OR EXAMINATION AS PER RULE

AACP

At present owing to damage  
Renewed on the Portside 3 outside plates below the  
topside. Two other plates taken off made fair & replaced  
& rivetted. Some keel & stempost rivets renewed.

Bottom Scraped & Grated.

Present Condition of the

Decks

Good

Greenails

Rivets

Good

Windlass and Capstan

Waterways

"

Breasthooks and Stemson

"

Pumps

Comings

"

Transoms, Pointers, and Crutches

"

Boats

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the openings

"

Masts, Yards, &c.

Lower Deck Beams & Fastenings

"

Ditto Ditto at other places

"

Condition, how ascertained

Sheers

"

Keelsons

"

Sails

Trunks

"

Ceiling

"

Anchors No. of 3 Bower

Stems

"

Rudder

"

Cables

Bottom

"

Copper

Coated

When put on

Now

Hawsers and Warps

(Bottom) and Counter

"

Caulking of

Good

Standing & Running Rigging

Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

General Observations, Opinion as to Class, &c.

She is now in an efficient state of repair  
and respectfully recommends her to remain as classed & the  
two Bower Anchors stated to be placed on board when on the  
act of sailing should be examined on her return voyage  
Note attached

The Amount of Entry Fee ...

£ 2 : 2 :

received by me,

22 Oct 1878

Special

£ 2 : 2 :

Certificate (if required) ...

£ 5 :

(Travelling Expenses, if any, £)

Committee's Minute

10th October,

1878

Character assigned

905  
TJW

Samuel Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
Foundation

IRON 480-0424