

21973  
**REPORT of SURVEY for REPAIRS, &c.**

No. 4396.

No. in Reg. Book. Survey held at *Cardiff* Date, first Survey Last Survey *30 Sept 1878*

1012 on the *S.S. Annie Minstie*

Master *Dwyer*

TONNAGE under Tonnage Deck *1314*

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Official Number

Ditto of Forecastle

Gross Tonnage *1326*

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St mer, cut on Bm. *847*

Built at *Stockton*

When built *1870*

YEAR.

MONTH.

Owners *Nelson, Jonsin & Co*

Port belonging to *Londro*

Residence *Newcastle*

By whom built *Parce*

Destined Voyage *New Orleans*

Surveyed Afloat or in Dry Dock *Will & B Dry Dock*

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. *20370*

Port *Iron*

Classed

*80.A.1*

*SP No 3.38*

REPAIRS, OR EXAMINATION AS PER RULE

*After grounding.*

*Placed on blocks in Dry Dock. Keel cleaned & coated externally*

Cause of Repairs to be clearly stated.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

*Vessel appears in good & efficient condition, eligible to remain as classed 80.A.1*

The Amount of Entry Fee ... ..£ : : received by me, *SAV.*

Special ... ..£ : : *1/10 1878*

Certificate (if required) ... ..£ : :

(Travelling Expenses, if any, £ )

Committee's Minute

22nd October, 1878,

Character assigned

*80.A.1*  
*SAV.*

*Henry J. Syrell.*  
Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 430-042-5





© 2019

Lloyd's Register  
Foundation