

REPORT of SURVEY for REPAIRS, &c.

No. 14400

No. in Reg. Book.

Survey held at

Date, first Survey

Last Survey

1878

on the

S.S. "Cambromne"

Master

YEAR.

MONTH.

TONNAGE under Tonnage Deck

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

Built at

When built

Owners

Port belonging to

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

Port

Classed

100 A. 1

REPAIRS, OR EXAMINATION AS PER RULE

in case of Damage.

Special Report

Now Done, the Sheer Strake Plate removed & refitted. Two Plates in 2nd Strake removed, also two plates in 5th Strake heated set to form & riveted, one plate in 1st Strake, and one plate in 4th Strake down renewed, also two Bulwark Plates, a length lower Deck Stringer plate renewed, new Butt Straps fitted, & Angle Irons on Stringer plate repaired & refitted, one length of upper Deck Stringer plate, rep^d and refitted with Angle Irons on the same, 40 feet of Main Rail, renewed with American Elm, and new Angle Irons fitted, six Bulwark Channels repaired & refitted, Fine Chain Plates, (the Riggers,) & 20 lbs. Angle Iron frame & reverse bar, repaired by new length, connected by bottom Angle Iron, and others straightened & repartened; Fine Half Beams, in way of the Hatch Way renewed, the Bulwark Beam taken out, set fair & refitted, Fine intercostal Angle Irons renewed between frames, upper Bilge Angle Iron repaired, Ceiling replaced where required; All the above on Starboard side between Bridge and Foremast.

Condition of the

Good

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper

Caulking of

Bottom, Deck, & Waterways

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Repairs having been executed as here reported, and vessel placed in good, and efficient condition, she is eligible in my opinion to remain as Classed 100 A. 1.

The Amount of Entry Fee

£ 2 : 4 : 0

received by me,

Special

£ 2 : 2 : 0

Certificate (if required)

£ : 5 : 0

Committee's Minute

29th October,

1878

Character assigned

100 A. 1

TRM D. 1878

Henry J. Verrill

Surveyor to Lloyd's Register of British and Foreign Shipping.

© 2019

Lloyd's Register Foundation

"Cambronne"

Vessel placed on Block in Dry Dock, Bottom well cleaned & coated
with Paint.

Henry J. Tyrrell



© 2019

Lloyd's Register
Foundation