

ANNUAL SURVEYS.

No. 388 Survey held at London Date, first Survey 19th Octr. Last Survey 24th Octr. 1878
 No. in on the Ship "John C. Munro" Master Summers
 Reg. Book. 388 Tonnage 613 Built at Sunderland When built 1862 11th mo.
 By whom built Laing Owners Killick, Martin & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock West Ind. Dry Dock

Last Survey, No. 18988 Port of Iron Classed _____ Years assigned _____ Character in Register Book. *A1
 Present Condition of the Decks Good Treenails Rivets Good where seen
 Waterways _____ Breasthooks and Stenson _____ do _____
 Comings _____ Transoms, Pointers, and Gratches _____ do _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ do _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ do _____
 Planksheers _____ Keelsons _____ do _____
 Sheerstrakes _____ Clamps and Shelves _____ do _____
 Topsides _____ Ceiling _____ do _____
 Wales _____ Rudder good _____
 Plank (Bottom) and Counter _____ Copper or F.M. Paint When put on now _____
 Caulking of Bottom, Deck, & Waterways good _____
 Engine Room Skylights _____ Coal Bunker, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. _____

Rudder pintles rebushed. - Bottom cleaned & repainted. -
Surveyed with ballast in hold. -

She is now in good, efficient condition & eligible in our opinion to remain as classed. -

Committee's Minute 1st November, 1878. H. Paulsen.
 Character assigned *A1 Thos. Congdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 798 Survey held at London Date, first Survey 23rd Octr. Last Survey 25th Octr. 1878.
 No. in on the S. S. "Envoy" Master H. E. Snow
 Reg. Book. 798 Tonnage 1031 Built at Hull When built 1872 1st mo.
 By whom built Gilbert Owners H. Liddell
 Port belonging to Hull Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Millwell Dry Dock

Last Survey, No. 19808 Port of Iron Classed _____ Years assigned _____ Character in Register Book. 90 A1
 Present Condition of the Decks Good Treenails Rivets Where seen Good
 Waterways _____ Breasthooks and Stenson _____ do _____
 Comings _____ Transoms, Pointers, and Gratches _____ do _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____ do _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____ do _____
 Planksheers _____ Keelsons _____ do _____
 Sheerstrakes _____ Clamps and Shelves _____ do _____
 Topsides _____ Ceiling _____ do _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or F.M. Paint When put on now _____
 Caulking of Bottom, Deck, & Waterways good _____
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers _____ Cargo and Main Hatchways good Hatches _____
 General Observations, Opinion as to Class, &c. _____

Bottom cleaned & recoated. - Surveyed with Cargo in hold. -

She is now in good, efficient condition & eligible in our opinion to remain as classed. -

Committee's Minute 1st November, 1878. H. Paulsen.
 Character assigned 90 A1 Thos. Congdon
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____