

Report of Survey for Repairs of Engines and Boilers.

No. 118 (Rev. 7/11/78)
 No. in Reg. Book. Survey held at Newcastle Date, first Survey 16th Last Survey 20th August 1878

409 on the Iron S.S. Teekwicks Master J. Dorrin


Tons 731 Owners G. Bell & Co Port belonging to North Shields Years assigned 90 Character in Register Book A1
1141 899

Diameter of Cylinders 27¹/₂ 50 Engines made at Hartlepool When made 1871
 Length of Stroke 30"
 Pressure of Steam 73
 Registered Horse Power 100 By whom made J. Richardson & Sons

Particulars of Repairs and Examination Repairs to Engines
High pressure cylinder bored out true, and new piston fitted also Engines generally overhauled.
The above repairs having been satisfactorily completed this vessel is now in good order and safe working condition and eligible in my opinion to retain her class in the Society's Register Book.

Amount of Fee ... £ ... received by me, Spring
 Certificate (if required) ... £ ... 2 Nov 1878
 Expenses, if any, £ —
 Committee's Minute 18

John Brockat
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



It is submitted that this
vessel is eligible to
remain as classed

Milton

8/11/78



© 2019

Lloyd's Register
Foundation