

ANNUAL SURVEYS.

22098-37646

Survey held at London Date, first Survey 30th Oct. Last Survey 30th October 1878
 in on the S.S. Assyria Master Alex. Hay
 Book. 60 Tonnage 940 Built at Renfrew When built 1872 - 5 no
 By whom built Simon Owners Brit. India Ste. Nav. Co.
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Shames Limited Dry Dock.

Last Survey, No. 20156 Port of Iron Classed ss. Lon N°1-76 Character in Register Book 100A1
 Condition of the Good Treenails Rivets Good
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling _____
 Rudder _____
 Coating on bottom Good When put on now
 Copper or P.M. _____
 Caulking of _____
 Bottom, Deck, & Waterways Good
 Windlass and Capstan _____
 Pumps _____
 Boats 5 no.
 Masts, Yards, &c. Good & Sufficient
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of 3B 15 & 24
 Cables _____
 Hawesers and Warps _____
 Standing and Running Rigging _____
 Hatches Good
 General Observations, Opinion as to Class, &c. Surveyed with Coals, &c. in hold
Bottom scraped and recoated. This vessel appears to be now in good and efficient condition and eligible to remain as at present classed.

Committee's Minute 15th November, 1878.
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

Survey held at London Date, first Survey 30 Oct. Last Survey 31 Oct. 1878
 in on the Ship "Star of France" Master S. Hughes
 Book. 234 Tonnage 1569 Built at Belfast When built 1877 - 11 no.
 By whom built Harland Owners J. Gatty & Co.
 Port belonging to Belfast Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Green's upper Dry Dock.

Last Survey, No. 20120 Port of Iron Classed _____ Character in Register Book 100A1
 Condition of the Good Treenails Rivets Good
 Breasthooks and Stemson _____
 Transoms, Pointers, and Crutches _____
 Timbers of the Frame at the Openings _____
 Ditto ditto at other places _____
 Keelsons _____
 Clamps and Shelves _____
 Ceiling (Ballast in hold)
 Rudder _____
 Coating on bottom Good When put on now
 Copper or P.M. _____
 Caulking of _____
 Bottom, Deck, & Waterways Good
 Windlass and Capstan _____
 Pumps _____
 Boats 4 no.
 Masts, Yards, &c. Good and Sufficient
 Condition, how ascertained _____
 Sails _____
 Anchors, No. of 3B 15 & 24
 Cables _____
 Hawesers and Warps _____
 Standing and Running Rigging _____
 Hatches Good
 General Observations, Opinion as to Class, &c. Bottom cleaned and recoated. This vessel appears to be now in good and efficient condition, and eligible to retain her present class.

Committee's Minute 15th November, 1878.
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____