

Report of Survey for Repairs of Engines and Boilers.

No. in Reg. Book. *4767* Survey held at *Glasgow* Date, first Survey *June 11th* Last Survey *Decr 2nd 1878*
973 on the *S.S. "Clutha"* Master *Robert Russell*
 Tons *337* Owners *J. Bell* Port belonging to *Glasgow* Classed *A1*
 515

Diameter of Cylinder *25 1/4"* Engines *Compound* When made *1878*
 Length of Stroke *30"* Pressure of Steam *65 lbs* By whom made *Muir & Houston*
 Registered Horse Power *95*

Particulars of Repairs and Examination *New Cylinders and Surface Condenser fitted
 Pumps all new. Link motion new. Crank shaft bearing overhauled
 & made good also Connecting Rods with brasses & Eccentric Shafts
 New Sea cocks & Valve Chests fitted, Propeller new. and Stern bush
 examined on ship.
 Boilers new.*

*The Blow-off cocks & Main Injection Valve Chest, moved
 from flat of bottom to upper turn of Bridge in compliance with
 the Society's Rules (Sec. 39)*

*The above repairs & alterations have been satisfactorily completed
 by Messrs Muir & Houston, and the Boilers & Machinery are now
 in good working condition & eligible in my opinion to be noted
 in the Register Book Lloyd M.C. 12/78.*

Amount of Fee ... £ 5 : " : " received by me, *J. Mollison*
 Certificate (if required) ... £ : : Decr 1878
 Submittee's Minute 18

The arrangement of pipes cocks & valves
in this vessel has now been altered
in accordance with the Rules
Sec. 39, and the vessel
appears eligible to be
granted a Machinery
Certificate and the
notification
Lloyd's MC 1278

M
10-12-78



© 2019

Lloyd's Register
Foundation