

Report of Survey for Repairs of Engines and Boilers.

No. *55* *Last Report: 18431* *Rec 29/4/78*
 No. in Reg. Book. *892* Survey held at *Nyall* Date, first Survey *22nd March* Last Survey *18th April 1878*
 on the *Iron Screw Steamer, Spartan* Master *Tatton*
 Tons *1263* Owners *M. Spartali* Port belonging to *London* Classed *12, 75*
 Years assigned. *12, 75* Character in Register Book. *A1*

Diameter of Cylinder *2' 36"* Engines made at *Port Glasgow* When made *1868*
 Length of Stroke *42* Pressure of Steam *40 lb per sq in* By whom made *Blackwood & Gordon*
 Registered Horse Power *150*

Particulars of Repairs and Examination


Now done on account of damage
Two new shafts fitted and one shaft straightened
in a lathe. each coupling provided with ten
couplingbolts and ten nut bolts 1 3/4" dia.
One plumbblock refastened
In my opinion can remain as closed

The Amount of Fee ... £ — : — : received by me, *Ally*
 Certificate (if required) ... £ — : — : *18. April 1878*
Damage Report £ 3. 3/.
 Travelling Expenses, if any, £

Committee's Minute

18

Ally
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
 Foundation

IRON 481-0577

Machinery has been damaged and repaired
Submitted that vessel is eligible to
remain as claimed

MD 29.4.78



© 2019

Lloyd's Register
Foundation