

# REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. **No. 23** Survey held at **Dundee** Date, first Survey **16 July** Last Survey **4 Sept 1878**  
**65 75** on the Ship **"Pamure"** Master **J. Downie**  
 Tonnage under Tonnage Deck **1396** Built at **Glasgow** When built **1875** YEAR. MONTH. **6**  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage **1581** Owners **S. Bruce & Co** Port belonging to **Dundee**  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam **1505** By whom built **Stephen** Destined Voyage **San Francisco**  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm.  
 If Surveyed Afloat or in Dry Dock **Afloat**  
 Length of Poop **40** ft. Ditto, Forecastle **37** ft. Ditto, Raised Quarter Deck  
 Last Survey, No. **20562** Port **Iron** Classed **100 A 1**  
 Years assigned. **3.78** Character in Register Book.

## REPAIRS, OR EXAMINATION AS PER RULE

This Ship on her passage to this port from London had her decks swept and received very considerable damage including loss of boats, skids &c. Cornices of deckhouse much started and part of bulwarks & rails carried away besides other serious damage. I was assisted in surveying this ship by Mr Sparrow iron ship builder & Mr McKeown Master Shipwright. And the whole of the repairs was effected under my inspection and to my entire satisfaction. The vessel was thoroughly reequipped and was in splendid condition when she left this Port. I may mention that the S.S. Hawea collided with the Pamure doing damage which was all properly repaired.

Present Condition of the  
 Decks **part new and all caulked** Treenails  
 Waterways Breasthooks and Stenson  
 Comings Transoms, Pointers, and Crutches  
 Upper Deck Beams & Fastenings Timbers of the Frame at the openings  
 Lower Deck Beams & Fastenings Ditto Ditto at other places  
 Planksheers Keelsons  
 Sheerstrakes Clamps and Shelves  
 Topsides Ceiling  
 Wales Rudder  
 Plank (Bottom) and Counter Copper When put on  
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers  
 General Observations, Opinion as to Class, &c. Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors No. of  
 Cables  
 Hawser and Warps  
 Standing & Running Rigging  
 Hatches

The Amount of Entry Fee ... £ **3** : - : - received by me, }  
 Special ... £ **7** : 7 : 16 Sep 1878 }  
 Certificate (if required) ... £ : : :  
 (Travelling Expenses, if any, £ )

Committee's Minute

Character assigned

written by  
 Dr 1/1/79

27th December, 1878

**100 A 1**  
**DBM**

**James W Russell**  
 Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register  
 Foundation

1804482-0052