

22495 ANNUAL SURVEYS.

37792
Recd 20-1-79

No. _____ Survey held at London Date, first Survey Jan 15 Last Survey Jan 17 1879
No. in on the SS Erasmus Wilson Master S Bond
Reg. Book. 815 Tonnage 487 Built at Hartlepool When built 1876-3
By whom built Withy Owners S Clarke & Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 20815 Port of HowClassed 90A 5.78.

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheerstrakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Coated</u> When put on <u>Now</u>	
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>
Cargo and Main Hatchways	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom scraped and coated.
She is now in good condition
and entitled to remain as classed.

Committee's Minute 21 st January, 1879.Character assigned 90A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____

No. _____ Survey held at London Date, first Survey Jan 2 Last Survey Jan 3 1879
No. in on the SS Taymouth Castle Master J Fulton
Reg. Book. 101 Tonnage 1172 Built at Glasgow When built 1877-3M
By whom built Barclay Owners D Currie & Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Thames Iron Works Dry Dock

Last Survey, No. 21458 Port of _____Classed 100A 9.78

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways	"	Breasthooks and Stemson	"
Comings	"	Transoms, Pointers, and Crutches	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"
Planksheers	"	Keelsons	"
Sheers'rakes	"	Clamps and Shelves	"
Topsides	"	Ceiling	"
Wales	"	Rudder	"
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Co</u> When put on <u>Now</u>	
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>
Cargo and Main Hatchways	<u>Good</u>	Hatches	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom scraped and coated.
She is now in good condition
and entitled to remain as classed.

Committee's Minute 21 st January, 1879.Character assigned 100A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required) _____ Paid _____ 18 _____