

22568 REPORT of SURVEY for REPAIRS, &c.

No. 12114

No. in
Reg. Book.

Survey held at

Date, first Survey

Last Survey

18 49

on the

Iron screw steamer "Medusa" Arming Dock

Master

Wright

YEAR.

MONTH.

TONNAGE under Tonnage Deck

1110

Ditto of Spar Deck, or Avoing Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1110

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

719

Built at

Sunderland

When built

1862

Owners

Mr. James Loring

Port belonging to

Sunderland

Residence

Sunderland

By whom built

Loring

Destined Voyage

Surveyed Afloat or in Dry Dock

at Cornhill River Quay

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. 20541

4885

Port

Sunderland

Classed

90 A.1

REPAIRS, OR EXAMINATION AS PER RULE

for annual survey

This vessel was placed in dry dock for the purpose of sighting and cleaning the bottom; which on examination was found to be in good condition. A few rivets of the rudder plating at the after part were renewed, and the bottom cleaned and recoated with patent composition. The load line of "14 feet," as sanctioned by the Committee, was indicated by a diamond in white paint, on a black ground, with a bar at each end and the letters T. R. as required by Circular Number 354.

Present Condition of the

Decks

good

Waterways

do

Comings

do

Upper Deck Beams & Fastenings

good

Lower Deck Beams & Fastenings

do

Planksheers

do

Sheerstrakes

do

Topsides

do

Wales

do

Plank (Bottom) and Counter

do

Engine Room Skylights

good

Coal Bunker, Openings, Lids, &c.

good

Scuppers

good

Cargo and Main Hatchways

good

Hatches

good

General Observations, Opinion as to Class, &c.

This vessel being in good and efficient condition she is in my opinion eligible to remain as classed

Freemasts

good

Breasthooks and Stemson

do

Transoms, Pointers, and Crutches

do

Timbers of the Frame at the openings

do

Ditto

Ditto

at other places

do

Keelsons

good

Clamps and Shelves

do

Ceiling

do

Rudder

do

Copper

do

When put on

do

Caulking of

Bottom, Deck, & Waterways

good

Windlass and Capstan

good

Pumps

good

Boats

do

Masts, Yards, &c.

do

Condition, how ascertained

from shell

Sails

complete

Anchors

No. of

3. B. 10. 2 1/2

Cables

not ranged

Hawsers and Warps

complete

Standing & Running Rigging

good

The Amount of Entry Fee ...

£

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

Special ...

£

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

Certificate (if required) ...

£

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

...

Committee's Minute

17th January,

1879.

Character assigned

90 A.1

TRW Arming Dock

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019
Lloyd's Register
Foundation

IRON482-0239