

ANNUAL SURVEYS.

22545

No. 26333 Survey held at Liverpool Date, first Survey Jan 2nd Last Survey Jan 4th 1879
 No. in on the Scw. Sr. "Sutherland" Master McKelvie
 Reg. Book. 1300 Tonnage 612 Built at Glasgow When built 1866 - 8 mo
 By whom built Barclay Owners D. Currie & Co
 Port belonging to London Destined Voyage Hamburg.
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock.

Last Survey, No. 20643 Port of Row Classed 100 AI
 Present Condition of the Decks Good Treenails Rivets. Good S.S. Cl. N°3-78. 3.78.
 Waterways 4 Breasthooks and Stems 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shells 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 11
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint & the vessel being now in a good and efficient condition is eligible in my opinion to remain as classed.

Committee's Minute Liverpool Jan^{ry} 24th 1879.
 Character assigned 100 AI.

J. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Jan 16th Last Survey Jan 21st 1879
 No. in on the Bark "Barraconta" Master D. Pender
 Reg. Book. 109 Tonnage 610 Built at Liverpool. When built 1864 - 7 mo.
 By whom built Evans. Owners W. Hilley & Co.
 Port belonging to Liverpool Destined Voyage Valparaiso.
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 16337 Port of Iron Classed * AI
 Present Condition of the Decks Good Treenails Rivets. Good S.S. Liv N°3-76. 8.76.
 Waterways 4 Breasthooks and Stems 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shells 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 648/68
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom sighted, cleaned and coated with paint and the vessel being now in a good and efficient condition is eligible in my opinion to remain as classed.

Committee's Minute Liverpool Jan^{ry} 24th 1879.
 Character assigned * AI.

J. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Sutherland^{ss}

Navracouta

16883.



© 2019

Lloyd's Register
Foundation