

REPORT of SURVEY for REPAIRS, &c.

No.

No. in
Reg. Book.

Survey held at

London

Date, first Survey Dec 7/78

Last Survey

Reg. 9-1-79

1879

535

on the

S Ellen Street

Master

J Reid

YEAR.

MONTH.

TONNAGE under Tonnage Deck

1120

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1648

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

1572

Built at

Liverpool

When built

1854

Owners

Stuart & Douglas

Port belonging to

Liverpool

Residence

By whom built

Destined Voyage

If Surveyed Afloat or in Dry Dock

Greens Dry Dock

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

19403

Port

Row

Classed

90A1 1177

SS Lon M23-74

REPAIRS, OR EXAMINATION AS PER RULE

SS M21

At the present time placed in dry dock
the timbers and ceiling equal to one, and more struts
in several places taken up exposing both surfaces of
plating, examined and found good. cement tested which
was adhering firmly to the iron.
Bottom outside scraped and coated.
The chain cables were all on deck and examined
last Special Survey, in 1874, as stated in the Report.
She has an Iron Patent Purchase for a Windlass.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Good

Treenails

Rivets

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

Good &

Sufficient

where

they

could

be seen

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Coated When put on

Caulking of

Bottom, Deck, & Waterways

Good

She is now in good condition

and entitled to remain as classed

and Marked SS M21-1879 in the Register Book.

Senhouse Martindale

The Amount of Entry Fee ...

...£

...

...

received by me,

187

Special

...£ 4 : 4 :

...

...

Certificate (if required)

...£

...

...

(Travelling Expenses, if any, £)

Committee's Minute

10th January,

1879.

Character assigned

90A1

SS M21-79



© 2019

Lloyd's Register
Foundation

IRON 482-0251