

REPORT of SURVEY for REPAIRS, &c.

No.

No. in
Reg. Book.

Survey held at London

Date, first Survey 21 Jan^y 1879 Last Survey 27 January 1879

(Recd 1.2.79)

25 on the BE Umzinto

Master J. Nurse

YEAR. MONTH.

TONNAGE under Tonnage Deck 265

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

Crew Space, as per Rule

Register Tonnage, put on Beam

Engine Room

Reg. Tons as St^rmer, out on Bm.

Built at Sunderland

When built 1871

MONTH.

Owners Ballard Key

Port belonging to London

Residence

By whom built Pile

Destined Voyage Natal

If Surveyed Afloat or in Dry Dock Below Dry Dock

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Years assigned.

Character in Register Book.

Last Survey, No. 21032

Port Port

Classed

100 A 1

S.S. Low No 1.75

5.78

REPAIRS, OR EXAMINATION AS PER RULE

For S.S. No 2

Vessel placed in dry dock and her bottom scraped and painted. The whole of the hatchels and loose ceiling in hold lifted, being in excess of Rule requirement for S.S. No 2. The iron work cleaned and cement washed - The cement found everywhere in good condition and closely adhering to the iron - Chain cables ran - Fire peak cleared. She has an iron windlass. Spars examined.

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plating

Plank (Bottom) and Counter

Good

Greenails Ruets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Paint When put on now

Caulking of

Bottom, Deck, & Waterways

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3 B 18 2 K

Cables 210 Fms - Good

Hawsers and Warps

Standing & Running Rigging

Good

Good

Good

Good

From aloft

Good

Engine Room Skylights

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

She is now in a good and efficient condition and the Rules for Special Survey No 2 having been complied with I am of opinion that she is eligible to remain as classed and to be noted S.S. Low No 2.79 in the Register Book.

The Amount of Entry Fee£ " : " : "

3/19 Special£ 4 : 4 : -

Certificate (if required)£ - : - : -

(Travelling Expenses, if any, £

Committee's Minute

4th February 1879

Character assigned

100 A 1

DMW S.S. No 2-79

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 482-0359