

ANNUAL SURVEYS. 224/25. 37.867

No. 28 Survey held at London Date, first Survey Feb 13 Last Survey Feb 13 1879.
 No. in on the SS Queen Margaret Master B Butler
 Reg. Book. 28 Tonnage 2044 Built at Glasgow When built 1875-5M
 By whom built San & Glas Co Owners Queen Steam Ship Co
 Port belonging to Glasgow Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Point Dry dock

Last Survey, No. 20860 Port of London Classed 100A-578

Present Condition of the
 Decks Good Treenails Rivet Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Covered When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

She is now in good condition and entitled to remain as classed.

Committee's Minute 18th February, 1879.

Character assigned 100A-578

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____

No. 21 Survey held at London Date, first Survey Jan 15 Last Survey Feb 11th 1879.
 No. in on the SS J M Strachan Master J Brown
 Reg. Book. 21 Tonnage 578 Built at Newcastle When built 1865-8M
 By whom built Palmer Owners S Clarke Esq
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St

Last Survey, No. 21184 Port of London Classed 678

Present Condition of the
 Decks Good Treenails Rivet Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Covered When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. _____

Oxidation shipped off inside & painted. The SS M1 survey was recommended in this case and the owner (through the Capt) informed me that he intends shortly to give her new boilers & would like the survey to be done then. She is in good condition & respectfully submit for the Committee favourable consideration to grant the owners request to allow her to remain as classed & SS M1 gone through when the boilers are taken out.

Committee's Minute 18th February, 1879.

Character assigned 678 as now

Senhouse Martin
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) _____ Paid _____ 18 _____