

ANNUAL SURVEYS.

No. 21 Survey held at London Date, first Survey 30. 1. 79 Last Survey 11. 2. 79 1879
 No. in on the Bk "Abby Town" Master Shaplan
 Reg. Book. 21 Tonnage 738 Built at P. Glasgow When built 1875 - 8 mo
 By whom built Hamilton Owners J. Hay & Co
 Port belonging to Liverpool Destined Voyage
 If Surveyed Afloat or in Dry Dock Dry dock & afloat

Last Survey, No. 19382 Port of MDN Classed 100 A.1.
 Present Condition of the Decks good Rivets wh. seen good
 Waterways do Breasthooks and Stemson do do
 Comings do Transoms, Pointers, and Crutches do do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do do
 Lower Deck Beams & Fastenings do Ditto ditto at other places not seen
 Planksheers Plating do Keelsons wh. seen good
 Sheerstrakes do Clamps and shafts do do
 Topsides do Ceiling do do
 Wales Plating do Rudder good
 Plank (Bottom) and Counter do Copper or Y.M. When put on
 Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers do
 General Observations, Opinion as to Class, &c. Vessel placed in dry dock, bottom cleaned and recoated with 2 coats of fine tone coat of Zinc & Tallow. Hold examined with Ballast - & part outward cargo therein. I am of opinion that the vessel is in a good condition and eligible to remain as classed.
 Committee's Minute 18th February, 1879.
 Character assigned 100 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DKW Paid 18

No. 33 Survey held at London Date, first Survey 4. 2. 79 Last Survey 14. 2. 79 1879
 No. in on the S. "Casarea" Master Barrette
 Reg. Book. 33 Tonnage 1257 Built at Sunderland When built 1877 - 4 mo
 By whom built Doxford Owners W. Pellier
 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock In Dry Dock

Last Survey, No. 10450 Port of MDN Classed 100 A.1.
 Present Condition of the Decks good Rivets wh. seen good
 Waterways do Breasthooks and Stemson do do
 Comings do Transoms, Pointers, and Crutches do do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do do
 Lower Deck Beams & Fastenings do Ditto ditto at other places not seen
 Planksheers Plating do Keelsons wh. seen good
 Sheerstrakes do Clamps and shafts do do
 Topsides do Ceiling do do
 Wales Plating do Rudder good
 Plank (Bottom) and Counter do Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers do
 General Observations, Opinion as to Class, &c. This vessel has been placed in dry dock, bottom cleaned and recoated with three coats of composition. Hold exam'd with part outward cargo therein. The vessel is now in good condition and is in my opinion eligible to remain as classed.
 Committee's Minute 18th February, 1879.
 Character assigned 100 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) DKW Paid 18