

ANNUAL SURVEYS.

22786

No. 26368

Survey held at Liverpool Date, first Survey Feb 6th Last Survey Feb 10th 1879.
 No. in on the Bark "H. Thelstan" Master E. Bayley
 Reg. Book. 211 Tonnage 771 Built at Harrington When built 1876 - 4 mo.
 By whom built Williamson Owners White Foreman & Co
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock

Last Survey, No. 19349 Port of

Classed 100 A1
 Years assigned. 9.77
 Character in Register Book.

Present Condition of the Decks Good Treenails Rivets. Good
 Waterways 4 Breasthooks and Stenson 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shells 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 76
 Engine Room Skylights ✓ Coal Bunker, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom examined cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed

Committee's Minute Liverpool Feb^{ry} 21 - 1879.
 Character assigned 100 A1.

T. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Feb 6th Last Survey Feb 8th 1879.
 No. in on the Ship "Edith Lorn" Master N. Watt.
 Reg. Book. 173 Tonnage 803 Built at Dundee When built 1876 - 1 mo
 By whom built Stephen Owners N. O. Taylor &
 Port belonging to Dundee Destined Voyage Iquique
 If Surveyed Afloat or in Dry Dock Clarence Dry Dock.

Last Survey, No. 19446 Port of Iron

Classed 100 A1
 Years assigned. 10.77
 Character in Register Book.

Present Condition of the Decks Good Treenails Rivets. Good
 Waterways 4 Breasthooks and Stenson 4
 Comings 4 Transoms, Pointers, and Crutches 4
 Upper Deck Beams & Fastenings 4 Timbers of the Frame at the Openings 4
 Lower Deck Beams & Fastenings 4 Ditto ditto at other places 4
 Planksheers 4 Keelsons 4
 Sheerstrakes 4 Clamps and Shells 4
 Topsides 4 Ceiling 4
 Wales 4 Rudder 4
 Plank (Bottom) and Counter 4 Copper or Y.M. Cement When put on 76
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Caulking of Bottom, Deck, & Waterways Good
 Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c.

Bottom examined cleaned and coated with paint, and the vessel being now in a good and efficient condition is eligible in my opinion to remain as Classed

Committee's Minute Liverpool Feb^{ry} 21 - 1879.
 Character assigned 100 A1.

T. Shilston.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

Ethelstan

Edith form.

26368.



© 2019

Lloyd's Register
Foundation