

ANNUAL SURVEYS.

22855 37.912

No. 553 Survey held at London Date, first Survey 19th Febr. Last Survey 21st Febr. 1879.
No. in on the Ship "Serapis" Master J. Pankhurst
Reg. Book. 553 Tonnage 995 Built at Greenock When built 1876 10th mo.
By whom built Scott Owners H. Lund
Port belonging to London Destined Voyage
☒ Surveyed ~~Afloat~~ or in Dry Dock Britannia Dry Dock.

Last Survey, No. 20215 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A11. 78

Present Condition of the

Decks

Good Transoms Rivets Good where seen

Waterways

Breasthooks and Stemsdo

Comings

Transoms, Pointers, and Crutchesdo

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openingsdo

Lower Deck Beams & Fastenings

Ditto ditto at other placesdo

Planksheers

Clamps and Shelves

Sheerstrakes

Ceilingdo

Topsides

Ruddergood

Wales

Copper or F.M. Paint When put on now

Plank (Bottom) and Counter

Caulking ofBottom, Deck, & Waterwaysgood

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.ScuppersCargo and Main HatchwaysHatches

General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.
Surveyed with ballast in hold.

Committee's Minute

7th March,1879.W. Paulsen

Character assigned

100 A1T.B.W.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18

No. 78 Survey held at London Date, first Survey 25th Febr. Last Survey 27th Febr. 1879.
No. in on the S. S. "Oceano" Master J. Walker
Reg. Book. 78 Tonnage 566 Built at Mdlsbr. When built 1871-8 mo.
By whom built Backhouse Owners Vatham & Co.
Port belonging to London Destined Voyage
☒ Surveyed ~~Afloat~~ or in Dry Dock Britannia Dry Dock.

Last Survey, No. 21413 Port of Iron

Classed

Years assigned.

Character in Register Book.

100 A19. 78

Present Condition of the

Decks

Good Transoms Rivets Good where seen

Waterways

Breasthooks and Stemsdo

Comings

Transoms, Pointers, and Crutchesdo

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openingsdo

Lower Deck Beams & Fastenings

Ditto ditto at other placesdo

Planksheers

Clamps and Shelves

Sheerstrakes

Ceilingdo

Topsides

Ruddergood

Wales

Copper or F.M. Black Varnish When put on now

Plank (Bottom) and Counter

Caulking ofBottom, Deck, & Waterwaysgood

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.goodScuppersCargo and Main HatchwaysHatches

General Observations, Opinion as to Class, &c.

Bottom cleaned & repainted.
Surveyed with ballast in hold.

Committee's Minute

7th March,1879.W. Paulsen

Character assigned

100 A1T.B.W.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required)

Paid

18