

# ANNUAL SURVEYS. 22978

No. 403. Survey held at Rotterdam Date, first Survey 6<sup>th</sup> March Last Survey 7<sup>th</sup> March 1879  
 No. in on the S.S. "Lord Byron" Master Jones  
 Reg. Book. 674. Tonnage 515/50/609 Built at 515/50/609 Stockton When built 1865 - July  
 By whom built Richardson Owners Palgrave, Murphy & Co  
 Port belonging to Dublin Destined Voyage  
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 22006 Port of Iron  
 Present Condition of the Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of Days Completely  
 Cables  
 Hawsers and Warps  
 Standing and Running Rigging

Engine Room Skylights good Coal Bunker, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good  
 General Observations, Opinion as to Class, &c. This vessel has been on the ground near the entrance of the Channel of Hellevoetsluis - I have sounded and sealed the pumps; but she leaked no water, tested the cement and found it in a good condition. So that I am of opinion this vessel is fit to carry dry and perishable cargoes to and from all parts of the world, and recommendable to remain in the Character A. 1 as classed.

Committee's Minute 25th March 1879  
 Character assigned  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18  
 No. in on the Master  
 Reg. Book. Tonnage Built at When built  
 By whom built Owners  
 Port belonging to Destined Voyage  
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed  
 Present Condition of the Decks  
 Waterways  
 Comings  
 Upper Deck Beams & Fastenings  
 Lower Deck Beams & Fastenings  
 Planksheers  
 Sheerstrakes  
 Topsides  
 Wales  
 Plank (Bottom) and Counter  
 Treenails  
 Breasthooks and Stemson  
 Transoms, Pointers, and Crutches  
 Timbers of the Frame at the Openings  
 Ditto ditto at other places  
 Keelsons  
 Clamps and Shelves  
 Ceiling  
 Rudder  
 Copper or Y.M. When put on  
 Caulking of Bottom, Deck, & Waterways  
 Windlass and Capstan  
 Pumps  
 Boats  
 Masts, Yards, &c.  
 Condition, how ascertained  
 Sails  
 Anchors, No. of  
 Cables  
 Hawsers and Warps  
 Standing and Running Rigging

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches  
 General Observations, Opinion as to Class, &c.

Committee's Minute 18  
 Character assigned  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) Paid 18