

REPORT of SURVEY for REPAIRS, &c.

No. in Reg. Book. No. 269. Survey held at Hamburg. Date, first Survey 12th Feb. Last Survey 15th February 1879.
268 on the S. S. "Penguin" Master Marshall

Official Number
TONNAGE under Tonnage Deck 729
Ditto of Spar Deck, or Awning Deck
Ditto of Poop, or Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 906
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St^rmer, cut on Bm. 582
Built at Dundee
When built 1867 5 mo.
Owners General Mm. Nav. Co. Port belonging to London
Residence London
By whom built Gourlay
Destined Voyage to London
If Surveyed Afloat or in Dry Dock Afloat

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
Classed 100 A 1
Last Survey, No. Port
6.77.

REPAIRS, OR EXAMINATION AS PER RULE

By collision the S. S. "Penguin" had with the S. S. "Bahia", her poop decks were broken in, also the sheerstrake and the strake next to it very much damaged on port side aft.

She has been temporarily repaired here.

On her sheerstrake an iron plate 5'6" X 2'6" X 1/16" and on the lower strake an iron plate 8" X 2'6" X 8/16" were placed. The other damage above the main deck on her poop also was temporarily repaired by double wood planking over fell.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchor No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
Engine Room Skylights	Caulking of	
Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways	
Scuppers		
Cargo and Main Hatchways		
Hatches		

General Observations, Opinion as to Class, &c.

She now, in my opinion, is fit to carry potatoes to London where she will be thoroughly repaired.

The Amount of Entry Fee ... £ : :
Damage Special ... £ 2 : 2 : 0.
Certificate (if required) ... £ : :
(Travelling Expenses, if any, £)

received by me, 15 Feb 1879

Emil Tadderatz
Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 18

Character assigned



© 2019

Lloyd's Register Foundation

120N484-0036