

ANNUAL SURVEYS.

No. 26454 Survey held at Liverpool Date, first Survey Apr 8th Last Survey Apr 9th 1874
 on the Sew "William Symington" Master Hallett
 Reg. Book. 381 Tonnage 1323 Built at Sunderland When built 1877 - 11 mo.
 By whom built Thompson Owners J. Marychurch & Co.
 Port belonging to Cardiff Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Sandon Dry Dock.

Last Survey, No. 22459 Port of Iron Classed 100 AI 1278.
 Present Condition of the Decks Good Good Good
 Waterways Good Breasthooks Good Transoms Good
 Comings Good Pointers Good and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Walks Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Cement When put on 27
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good

Bottom sighted, cleaned and coated with paint and the vessel being now in a good & efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool May 2nd 1879.
 Character assigned 100 AI. CDW

J. Shilston
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. ✓ Survey held at Liverpool Date, first Survey Apr 16th Last Survey Apr 17th 1879
 on the Bark "North Carolina" Master A. Buchan
 Reg. Book. 349 Tonnage 553 Built at Dumbarton When built 1876 - 10 mo.
 By whom built Mc Millan Owners Patton Vickers & Co.
 Port belonging to Liverpool Destined Voyage Bermuda
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 17344 Port of Iron Classed 100 AI 1176.
 Present Condition of the Decks Good Good Good
 Waterways Good Breasthooks Good Transoms Good
 Comings Good Pointers Good and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Plank (Bottom) and Counter Good Rudder Good
 Copper or Y.M. Cement When put on 76
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights ✓ Coal Bunkers, Openings, Lids, &c. ✓ Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Good

Bottom sighted, cleaned and coated with paint and the vessel being in a good and efficient condition is eligible in my opinion to remain as Classed.

Committee's Minute Liverpool May 2nd 1879
 Character assigned 100 AI CDW

J. Shilston
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

William Synnigton
North Carolina

264574



© 2019

Lloyd's Register
Foundation