

ANNUAL SURVEYS.

No. 107 Survey held at London Date, first Survey 15th May Last Survey 16th May 18 79
 No. in on the Barque "Barossa" Master H. F. Walker.
 Reg. Book. 107 Tonnage 968 Built at Sunderland When built 1873 - 5 mo.
 By whom built Pile Owners T. B. Walker
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Lineholm by Lock.

Last Survey, No. 21063 Port of London Classed 100 A.1.
 Present Condition of the
 Decks Good Trunnails Rivets Good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wals — Rudder —
Plate Copper or Y.M. Cement When put on —
Plank (Bottom) and Counter — Caulking of
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom examined, cleaned and coated with Patent Composition, and the topsides with Paint.
This Vessel is now in good and efficient condition, and eligible to remain as Classed.

Committee's Minute 3rd June, 18 79.
 Character assigned 100 A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 15 Survey held at London Date, first Survey 19th May Last Survey 21st May 18 79
 No. in on the S. S. "Rochdale" Master W. H. Hicks.
 Reg. Book. 15 Tonnage 961 Built at South Shields When built 1878 - 6 mo
 Supp 1420 By whom built Readhead Owners P. Hick Junr & Co.
 Port belonging to Scarboro Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Union by Lock.

Last Survey, No. 21457 Port of London Classed 100 A.1.
 Present Condition of the
 Decks Good Trunnails Rivets Good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wals — Rudder —
Plate Copper or Y.M. Cement When put on 1878
Plank (Bottom) and Counter — Caulking of
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted cleaned and coated with Paint and Tallow.

This Vessel is now in good and efficient condition and eligible to remain as Classed.

Committee's Minute 3rd June, 18 79.
 Character assigned 100 A.1.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18