

Report of Survey for Repairs of Engines and Boilers.

No. 2606

No. in Reg. Book. Survey held at

Belfast

Date, first Survey April 30th East Survey April 30th 1879

on the

S. S. "South Western"

Master

Prodie

Tons

460
260

Owners

Adriossan Shipping Co.

Port belonging to

Adriossan

Classed

Years assigned.

Character in Register Book.

1000A1
6.44

Diameter of Cylinder 28" x 30"

Length of Stroke

30"

Engines made at

Port Glasgow

When made 1870

Pressure of Steam

55 lbs.

Registered Horse Power

120

By whom made

Wm. Blackwood & Gordon

Particulars of Repairs and Examination General examination of Engines, Pumps, pipes & Noses. Sea cocks & valves examined. Screw Shafting & Stern Bush examined from the inside vessel being afloat at time of Survey.

Boilers examined throughout and several tubes now renewed. Safety valves and all connections examined. Previous to this survey several patches have been fitted on the furnaces and liners on circumferential seams at the bottom of the shell all of which appear to be well fitted.

The Engines & Boilers are now in good working condition and eligible in my opinion to be noted in the Register Book Lloyd's M.C. 5.79 for twelve months.

The Amount of Fee ... £ 2 : 2 : 0 received by me,

Certificate (if required) ... £ : : 12/5-1879

(Travelling Expenses, if any, £ 2-2-0)

Committee's Minute

18

James Morrison
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



The Engines and Boilers of this vessel have been
examined and repaired and are recommended to
have Lloyd's M.C. for 12 months, but it is
noticed that the Cochrane Rules are
not fitted in accordance with the
rules submitted that Mr. Molten
be asked how it is that he
recommends this vessel to have
Lloyd's M.C. when his cochrane
rules paper do not
comply with the rules

W
20.5.77



© 2019

Lloyd's Register
Foundation