

REPORT of SURVEY for REPAIRS, &c.

No. 4618 (Received at London Office, 18th July 1879)
 No. in Survey held at Penarth Date, first Survey
 Reg. Book. 486 on the S.S. "Black Watch" Last Survey 18th July 1879
 Master Macpherson
 TONNAGE under Tonnage Deck 1378 Built at Middleton When built 1874
 Ditto of Spar Deck, or Avoing Deck
 Ditto of Poop
 Ditto of Raised Qr. De.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 1485 Owners Young & Christies Port belonging to Cardiff
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 936 By whom built Cixon Destined Voyage New York
 Official Number 1485 Surveyed Afloat or in Dry Dock On New Gridiron (Penarth)

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft. Years assigned. _____ Character in Register Book. _____

Last Survey, No. 22473 Port Lyons Classed 100 A1
 REPAIRS, OR EXAMINATION AS PER RULE On acct of Damage (Special Report)

Placed on Gridiron for examination of Bottom, which appeared in good condition, with the exception of abrasion of paint in some places, now recoated with Paint & Sallow.
 Some Iron Rails & Stanchions on Poop Deck repaired, Sky light and other Deck fittings made efficient -
 One Lowline and one Hawler supplied.

Present Condition of the				
Decks	Good	Freenails	Paint wherever Good	Windlass and Capstan
Waterways	"	Breasthooks and Stenson	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained
Planksheers	"	Keelsons	"	2 or 3 feet
Sheerstrakes	"	Clamps and Shelves	Strainers &c	Lofer
Topsides	Plating	Ceiling	"	as seen
Wales	"	Rudder	"	Good
Plank (Bottom) and Counter	"	Copper (or Znc.)	Paint When put on	Good
Engine Room Skylights		Caulking of	Good	and
Coal Bunker, Openings, Lids, &c.		Bottom, Deck, & Waterways	Good	Eff't.
Scuppers		Cargo and Main Hatchways		
Hatches				

General Observations, Opinion as to Class, &c.
 The vessel now appears to be in good & efficient condition, eligible to remain as classed 100 A1.

The Amount of Entry Fee ... £ 2 : 2 : received by me, H. J. J.
 Special ... £ 1 : 1 : 18 1879
 Certificate (if required) to be sent as per margin... £ : :
 (Travelling Expenses, if any, £)

Henry J. Yerrall
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute 5th August, 1879.
 Character assigned 100 A1
TRW



[4,000-28/4/79.] (The Surveyors are requested not to write on or below the space for Committee's Minute.)

REPORT OF "Black Watch" REPAIRS & CO.

Handwritten text on lined paper, including names like "Black Watch" and "Repairs & Co." and various entries. The text is mirrored across the page, suggesting bleed-through from the reverse side. There are several large, irregular white patches on the right side of the page, likely from tape or damage to the original document.