

REPORT of SURVEY for REPAIRS, &c.

No. 737 on the SS Britannia (Received at London Office, Recd 12.8.79)

No. in Survey held at London Date, first Survey June 1st Last Survey Aug 29th 1879.

Reg. Book. 1272 Master J Hamilton

1343 on the SS Britannia YEAR. MONTH. 8

TONNAGE under Tonnage Deck 1272 Built at Sunderland When built 1875

Ditto of Spar Deck, or Awning Deck 1400 Owners Hamilton Bros Port belonging to Liverpool

Ditto of Poop 1343 Residence Asbourne Destined Voyage Colombo

Ditto of Raised Qr. Dk. 1343 By whom built Asbourne If Surveyed Afloat or in Dry Dock Greens Dry Dock

Ditto of Houses on Deck 1343 Length of Poop 44 ft. Ditto, Forecastle 34 ft. Ditto, Raised Quarter Deck 3 ft.

Ditto of Forecastle 1343 Last Survey, No. 19144 Port Iron Years assigned. 100 Character in Register Book. 100 A-9.77

Gross Tonnage 1400 REPAIRS, OR EXAMINATION AS PER RULE SS No 1.

Crew Space, as per Rule 1343 Cause of Repairs to be clearly stated.

Engine Room 1343

Reg. Tons as St^rmer, cut on Bm. 1343

At the present time the vessel placed in Dry Dock the timbers and ceiling equal to and above one shake lifted on both sides examined and found good cement tested which was adhering firmly to the iron. Scraped and coated.

Owing to damage Renewed Starboard side 23 Planks in the main deck Yellow Pine, 2 planks next to funnel Angle Iron East Main Deck. Midship & Isopallant Rails of E I Deck. 6 Bulwark plates. Deck caulking and Deck fittings.

Present Condition of the		Treenails	Rivets		new	East India Deck	
Decks	Good	Breasthooks and Stemson		Good	Windlass and Capstan		Good
Waterways	"	Transoms, Pointers, and Crutches		"	Pumps		"
Comings	"	Timbers of the Frame at the openings		"	Boats		"
Upper Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Masts, Yards, &c.		"
Lower Deck Beams & Fastenings	"	Keelsons		"	Condition, how ascertained		Sound
Planksheers	"	Clamps and Shelves		"	Sails		Good
Sheerstrakes	"	Ceiling		"	Anchors No. of 3 Bcs. 11 & 12		Good
Topsides	"	Rudder		"	Cables Packed on 8th		Good
Wales	"	Copper (or T.M.) Coated When put on		Good	Hawsers and Warps		"
Plank (Bottom) and Counter	"	Caulking of		Good	Standing & Running Riggings		"
Engine Room Skylights	✓	Bottom, Deck, & Waterways		Good	Cargo and Main Hatchways	Good	Hatches Good
Coal Bunker, Openings, Lids, &c.	✓						
Scuppers	Good						

General Observations, Opinion as to Class, &c.

She is now in good condition and entitled to remain as classed and Marked SS No 1. 1879.

Survey Fee £ 4 - 4 - 0

The Amount of Entry Fee ... £ 5 : 5 : 0 received by me, 15/8/79

13/8/79 Special ... £ 5 : 5 : 0

Certificate (if required) to be sent as per margin... £ 5 : -

(Travelling Expenses, if any, £)

Committee's Minute

15th August, 1879.

Character assigned

100 A-9.77

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation

IRON 187-0106