

# ANNUAL SURVEYS.

No. 4004 Survey held at South Shields Date, first Survey and Last Survey 30<sup>th</sup> August 1879  
No. in on the Iron S.S. "Dana" Master A. Mortensen  
Reg. Book. 39 Tonnage 644 Built at Malmö When built 1875-6 two  
By whom built Kockums Owners Stm Compania Dana  
Port belonging to Elseneur Destined Voyage Cronstadt  
If Surveyed Afloat or in Dry Dock Afloat Dry Dock

Last Survey, No. 24348 Port of Iron Classed 578  
Present Condition of the  
Decks Good. Treenails Rivets Good.  
Waterways do. Breasthooks and Stemson do.  
Comings do. Transoms, Pointers, and Crutches do.  
Upper Deck Beams & Fastenings do. Timbers of the Frame at the Openings do.  
Lower Deck Beams & Fastenings do. Ditto ditto at other places do.  
Planksheers do. Keelsons do.  
Sheerstrakes do. Clamps and Shelves Stringers do.  
Topsides do. Ceiling do.  
Wales do. Rudder do.  
Plank (Bottom) and Counter do. Copper or Y.M. ✓ When put on ✓  
Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Secure Hatches Good  
General Observations, Opinion as to Class, &c. This vessel has been surveyed both outside and inside where practicable, and found in good and efficient condition, and eligible in my opinion to remain as classed.  
The Owner's representative states that she will be docked and submitted to the S.S. Act in a few months time.

Committee's Minute 21/9/79 18 J. H. Cooke  
Character assigned GOOD Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required) Paid 18

No.        Survey held at        Date, first Survey        Last Survey        18         
No. in on the        Master         
Reg. Book.        Tonnage        Built at        When built         
By whom built        Owners         
Port belonging to        Destined Voyage         
If Surveyed Afloat or in Dry Dock         
Last Survey, No.        Port of        Classed         
Condition of the  
ays        Treenails         
s        Breasthooks and Stemson         
Deck Beams & Fastenings        Transoms, Pointers, and Crutches         
Deck Beams & Fastenings        Timbers of the Frame at the Openings         
eers        Ditto ditto at other places         
akes        Keelsons         
s        Clamps and Shelves         
ales        Ceiling         
ank (Bottom) and Counter        Rudder         
ine Room Skylights        Copper or Y.M.        When put on         
neral Observations, Opinion as to Class, &c.        Caulking of         
       Bottom, Deck, & Waterways        Standing and Running Rigging         
       Cargo and Main Hatchways        Hatches       

Committee's Minute 2nd September, 1879.  
Character assigned        Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required)        Paid        18