

24449 Iron

in the outside bottom plating renewed, and many ribs
in the inner double bottom plating & the plates taken off
ribs replaced & rivetted.

13 Planks in Main Deck renewed of Yellow Pine.

Double Bottom tested to tight line, wood ceiling
relaid & part new. Main Deck caulked where required.

Chain cables ranged & examined, & Windlass working
& wood lining stripped last Special Survey in 1874.

Senhouse Martindale
Mellor & Co. Davey



© 2019

Lloyd's Register
Foundation