

REPORT of SURVEY for REPAIRS, &c.

38148. Survey held at London Date, first Survey Aug 13th Last Survey Sept 19th 1879
 on the BK Whittington Master Mr. Webster
 Tonnage under Tonnage Deck 854 Built at Lancaster When built 1866
 Ditto of Spar Deck, or Awning Deck Owners Lancaster Shipbuilders & Co Port belonging to Lancaster
 Ditto of Poop Residence
 Ditto of Raised Or. Deck By whom built Lanc. Sh. B. Co Destined Voyage Philadelphia
 Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock.
 Gross Tonnage 970
 Crew Space, as per Rule 990
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St. mer cut on Bm.

Length of Poop 48 ft. Ditto, Forecastle 28 ft. Ditto, Raised Quarter Deck 6 ft. Years assigned. 378 Character in Register Book.
 Last Survey, No. 10663 Port Iron Classed A1
 SS Liverpool No 274

REPAIRS, OR EXAMINATION AS PER RULE SS No 3.

At present placed on the Pontoon
 the hold cleared and all the hold ceiling from
 the middle line keelson to top of bilges taken up on
 both sides all fore & aft exposing both surfaces of
 plating examined and found good,
 oxidation cut and beaten off cement tested which
 was adhering firmly to the iron.
 The plating is being so satisfactory it was not deemed
 necessary to drill them. She has a gutter furnace
 & no Wood Waterways. Cement thickened and mended
 where worn thin. Ceiling relaid and part new
 coated inside and out.

Present Condition of the									
ks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good			
Waterways	"	Breasthooks and Stemson		"	Pumps	"			
ings	"	Transoms, Pointers, and Crutches		"	Boats	"			
er Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	"			
er Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	Sound			
unksheers	"	Keelsons		"	Sails	Good			
erstrakes	"	Clamps and Shelves		"	Anchors No. of 3 Bbs. 12 & 14 lbs	"			
sides	"	Ceiling		"	Cables Part on deck	Good			
les	"	Rudder		"	Hawsers and Warps	"			
nk (Bottom) and Counter	"	Copper Coated When put on	Now		Standing & Running Rigging	"			
ine Room Skylights		Caulking of							
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good						
Scuppers	Good								
Cargo and Main Hatchways	Good								
Hatches	Good								
General Observations. Opinion as to Class, &c.									

She is now in good condition
 and eligible to remain as as classed
 and Marked SS No 3-1879 in Register Book.

Amount of Entry Fee ... £ 5 : 5 : 0 received by me, W. E. Dacey
 11/9/79 Special ... £ 5 : 5 : 0
 Certificate (if required) ... £ 5 : 5 : 0
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Committee's Minute 23rd September, 1879.
 Character assigned SS No 3-79
 J. W.



1879-0244

W. H. Miller



© 2019

Lloyd's Register
Foundation