

Change of Owners 244487
REPORT of SURVEY for REPAIRS, &c.

No. 26654
No. in Survey held at Liverpool Date, first Survey Aug 8th Last Survey Sep 19th 1879
Reg. Book. 229 on the Ship "Deva" Master J. G. Robinson
Official Number 19288
TONNAGE under Tonnage Deck 770
Ditto of Spar Deck, or Avoing Deck
Ditto of Poop
Ditto of Raised Qr. Deck
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 798
Crew Space, as per Rule
Register Tonnage, put on Beam 761
Engine Room
Reg. Tons as St^rmer, cut on Bm.
Built at Liverpool When built 1873 - 5
Owners Wm Rankin Port belonging to Greenock
Residence Greenock
By whom built Royden Destined Voyage
If Surveyed Afloat or in Dry Dock Blunswick Dry Dock & Afloat
Length of Poop ✓ ft. Ditto, Forecastle ✓ ft. Ditto, Raised Quarter Deck 42 ft. Years assigned. 100 Character in Register Book. FL
Last Survey, No. 19938 Port Gron Classed S.S. No 1-77 12.77
REPAIRS, OR EXAMINATION AS PER RULE
Cause of Repairs to be clearly stated.

This vessel received considerable damage at Valparaiso in 1878 by the tidal wave, where she was sold in her damaged state for the benefit of all concerned - After her sale, she was repaired by her new owners, and brought a cargo to this port, where she repairs, principally to the port bow and quarter have been thoroughly examined and found to have been effected in a satisfactory manner - The bottom has been cleaned and coated with paint -

Present Condition of the	Good	Treeails	Rivets.	Good	Windlass and Capstan	Good
Decks						
Waterways	✓	Breasthooks and Stem		✓	Pumps	✓
Comings	✓	Transoms, Pointers, and Crutches		✓	Boats	✓
Upper Deck Beams & Fastenings	✓	Timbers of the Frame at the openings		✓	Masts, Yards, &c.	✓
Lower Deck Beams & Fastenings	✓	Ditto Ditto at other places		✓	Condition, how ascertained	from on board
Planksheers	✓	Keelsons		✓	Sails	Good
Sheerstrakes	✓	Clamps and Shelves		✓	Anchors No. of	3 B - 1 S - 2 H
Topsides	✓	Ceiling		✓	Cables	16 in Good
Wales	✓	Rudder		✓	Hardware and Warps	and
Plank (Bottom) and Counter	✓	Copper (on V.M.) Cement	When put on	73.	Standing & Running Rigginy	Sufficient
Engine Room Skylights	✓	Caulking of		Good	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	✓	Bottom, Deck, & Waterways		Good	Hatches	Good
Scuppers	✓			Good		

General Observations, Opinion as to Class, &c.

This vessel is now in a good and efficient condition eligible in our opinion to remain as Classed -

The Amount of Entry Fee ... £ 1 : 0 : 0 received by me, A. D. Crook
Special ... £ 5 : 5 : 0 19/9/1879
Certificate (if required) } £ : 5 : 0
to be sent as per margin...

(Travelling Expenses, if any, £

Committee's Minute Liverpool Sept. 19th 1879

Character assigned 100 A1 - Record drp. 79 & Co

T. Shilstone
Surveyor to Lloyd's Register of British and Foreign Shipping.


E. Wheeler

Lloyd's Register
Foundation

REPORT of SURVEY for REPAIRS &

Deva

26657



© 2019

Lloyd's Register
Foundation