

ANNUAL SURVEYS.

No. 30446 Survey held at London Date, first Survey Sept 13 Last Survey Sept 5th 1877
 No. in on the SS Manora Master Coxens
 Reg. Book. 2120 Built at Sumbarton When built 1878, S.M.
 By whom built Senay Owners J Macneil & P Senay
 Port belonging to Glasgow Destined Voyage
 If Surveyed Afloat or in Dry Dock Bottom Victoria St

Last Survey, No. 22466 Port of Iron Classed 100A 2.77
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated.

She is now in good condition and entitled to remain as classed

Committee's Minute 16th September 1879.
12. 9. 79
 Character assigned 100A

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. 20365 Survey held at London Date, first Survey July 3 Last Survey July 31 1877
 No. in on the SS Almora Master Leg
 Reg. Book. 1744 Built at Sumbarton When built 1878 - S.M.
 By whom built Senay Owners Brit India Steamer Nav Co
 Port belonging to Glasgow Destined Voyage India
 If Surveyed Afloat or in Dry Dock Bottom Victoria St

Last Survey, No. 20365 Port of Iron Classed 100A 4.78
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on Now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated

She is now in good condition and entitled to remain as classed.

Committee's Minute 16th September 1879.
12. 9. 79
 Character assigned 100A

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18