

ANNUAL SURVEYS.

No. 38504 Survey held at London Date, first Survey 11th Sept Last Survey 11th Sept 1879
 No. in on the S. S. "Craigforth" Master Farmer
 Reg. Book. 1425 Tonnage 263 Built at Glasgow When built 1869 - 6 mo
 By whom built Lou & Glas Co. Owners C. Williamson.
 Port belonging to Leith Destined Voyage Sanube
 If Surveyed Afloat or in Dry Dock Princes Dry Dock

Last Survey, No. 21929 Port of Iron Classed S. S. Liv No 2-78. Years assigned. 10-78. Character in Register Book. A. 1.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wale — Rudder —
 Plate — Copper or Y.M. Cement When put on 1869
 Plank (Bottom) and Counter — Caulking of
Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunker, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom examined, one defective deck plank on starboard side, several bulks pierced and made good, Vessel now in good and efficient condition and eligible to remain as classed.

Committee's Minute 26th September, 1879. Thos Wm Blapell.
 Character assigned TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18 —

No. — Survey held at London Date, first Survey 19th Sept Last Survey 23rd Sept 1879
 No. in on the Barge "Amzinto" Master J. Nurse
 Reg. Book. 25 Tonnage 304 Built at Sunderland When built 1871 - 10 mo
 By whom built Pile Owners Bullard, King & Co.
 Port belonging to London Destined Voyage Natal
 If Surveyed Afloat or in Dry Dock Horseferry Dry Dock

Last Survey, No. 22660 Port of Iron Classed S. S. Liv No 2-79. Years assigned. 1-79. Character in Register Book. 100 A. 1.
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways — Breasthooks and Stems —
 Comings — Transoms, Pointers, and Crutches —
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings —
 Lower Deck Beams & Fastenings — Ditto ditto at other places —
 Planksheers — Keelsons —
 Sheerstrakes — Clamps and Shelves —
 Topsides — Ceiling —
 Wale — Rudder —
 Plate — Copper or Y.M. Cement When put on 1871
 Plank (Bottom) and Counter — Caulking of
Bottom, Deck, & Waterways Good
 Engine Room Skylights — Coal Bunker, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom sighted, Rudder unhung and bushed, bottom cleaned and coated with Paint & Tallow, Vessel now in good and efficient condition and eligible to remain as classed.

Committee's Minute 26th September, 1879. Thos Wm Blapell.
 Character assigned 100 A. 1. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) — Paid — 18 —